

TEST CERTIFICATE

Site Number
Transaction Number

03.A Other

840-Emirates Auctions

Transaction Date

12 Oct 2021, 17:11:19

اخري

16293094 (CC10006)

Queue Number

312309



Chassis Number JN8AY2NY9D9067404

Engine Number

Vehicle Class Car

Manufacturer **Nissan**

Model Patrol

Model Year **2013**

Color Black

Mileage 90800 Km

Fuel Type Petrol

No. Of Cylinders

Specification GCC Specification

8

DEFECT REMARKS

01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFIITED & REAR BOTH SIDE REPAIRED, REPAINTED	مدكار
01.B Doors	LEFT SIDE BOTH REPAINTED	أبواب
01.C Rusty	UNDER BODY PARTS, SUSPENTION , CHASSIS FRAME GETTING RUSTY	صدأ
01.D Bumper	REPAINTED	دعامية
01.E Bonnet	REFITTED	غطاء المحرك
01.F Other	FRONT FENDER FRAME, BUMPER FRAME, RADITOR SUPPORT BULK HEAD REPAIRED	اخري
01.G Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
02 Chassis Condition		الشاصي
02.A Chassis	FRONT BOTH SIDE CHASSIS, MOUNT BRACKET,SUSPENSION SUB FRAME CROSSMEMBER HEATED REPAIRED	الشاسيه
03 Engine Condition		المحرك

ОК

DEFECT	REMARKS	
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2019/2020	الاطار الامامي
04.B Rear Tyre	BOTH 2019	الاطار الخلفي
05 Transmission Condition		الجير
05.A Gear Box	OK	الجير
06 Brake Condition		الفرامل
06.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
07 Suspension System		ممتص الصدمات
07.A Arms	FRONT BOTH SIDE LOWER ARMS BUSHES CUT & GETTING RUSTY	ازرع
07.B Suspension Subframe	SUSPENTION SUB FRAME GETTING RUSTY	
08 Interior Condition		الاجزاء الداخلية
08.A Other	ОК	اخري
08.B Mirror	ОК	المرايا
08.C AC Condition	OK	المكيف
09 Lights		الاضاءة
09.A Head Light	ОК	الاضاءة الرئيسية
09.B Other	ОК	اخري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate









Transfer Certificate: 64961830 Chassis No: IN8AY2NY9D9067404 Vehicle Make: NISSAN Vehicle Model: PATROL Vehicle Class: Light Vehicle **Body Type: STATION** Fuel: Benzene Color: Black **Drive Direction:** Dimensions: (H x W x L) --x--x--**Current Odometer:** 90798 Kms Origin: Japan Model Year: 2013 **Engine Size:** 5600 CC Gear Type: Engine No: VK568999... Horse Power: 400 Axles No: 2 Cylinders: No Of Doors: 5 No Of Seats: 8 G. V. W.: Empty Weight: 2600 Kgs. 3300 Kas

Certificate Number: 5-TAS-2021-15209963 Inspection Date: 11-10-2021 Certificate Print Date : 11-10-2021 Services: Registration Test Vehicle Testing Partner: Tasjeel Vehicle Testing Center: Tasjeel Al Aweer Total Time Taken: 13 min 53 sec Appointment Ref Number : --Start Time: 11:48 End Time: 12:02 Lane: Token No.: 127 Prints No: 1 Attempt: 1

Carbon footprint



Your immediate action to protect Dubai environment is required

Estimated Vehicle Consumption (Rate last 12 Months)









64414 KMDistance per year

Fuel consumed per year

Fuel cost per vear

15.9 ton
Carbon footprint
per year

Parameter Readings

Service brake imbalance on front axle

15 %

Service brake imbalance on rear axle 17 %

Parking brake imbalance between LHS and RHS 22 % Vehicle on Petrol CO Reading

Vehicle on Petrol HC Reading O PPM VOL

Inspection Remarks:

FRONT BUMPER ,BUMPER FRAME ,BULK HEAD REPAIRED,UNDER NEATH RUST PROOFED.FRONT BOTH CHASSIS,MOUNT BRACKET HEATED REPAIRED & CROSS MEMBER REPLACED...PASSED CCM WORK ORDER 2021-10-10-7



Payment Details

Inspection Performed by 37084

Parking Slot No

--

Payment Method
Cash

Service Name Registration Test

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations

Transaction Number 15209963

Attempt 1

Service Fees

AED 170 Collected on 11/10/2021

Received by
Bajurdeen Abdul Gafoor

- 🚯 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال .30. يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.