



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>11 Sep 2022, 17:02:53</b>
Transaction Number	<b>73216960 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>SCA1S68095UX00371</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Rolls Royce</b>
Model	<b>Phantom</b>
Model Year	<b>2006</b>
Color	<b>White</b>
Mileage	<b>39773 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>12</b>
Specification	<b>USA Imported</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT BOTH SIDE FIBER PAINT CANNOT CHECK & REAR RIGHT SIDE PORTION REPAIRED, REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED, DENTS, SCRATCHES ON BODY	الصبغ
01.C Trunk	REPAIRED, REPAINTED	صندوق
01.D Bonnet	OPEN CABLE NOT FIXING PROPERLY LOOSE.	غطاء المحرك
01.E Doors	FRONT BOTH SIDE & REAR RIGHT SIDE PORTION REPAIRED, REPAINTED	أبواب
01.F Floor	UNDER BODY COVERD & ONLY VISIBLE AREA CHECK	الارضية
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Front Tyre	BOTH SIDE 2022	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
<b>03 Interior Condition</b>		<b>الحاله الداخليه</b>
03.A AC Condition	OK	المكيف
03.B Dash Board	DASH BOARD & BOX COVER LOOSE	لوحة القيادة
03.C Power Window Switch	LOCK DOOR BUTTON NOT WORKING	مفتاح النافذه

DEFECT	REMARKS	
<b>04 Chassis Condition</b>		<b>الشاصي</b>
04.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Visual Gear Box Condition	OK	حالة الجير النظرى
05.B Road Test	NOT CHECK	فحص علي الطريق
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	LOWER ARM BUSHES CUT	ازرع
<b>07 Steering Condition</b>		<b>المقود</b>
07.A Steering Boot	BOOT CUT	ربلة المقود
<b>08 Engine Condition</b>		<b>المحرك</b>
08.A Visual Engine Condition	OK	حالة المحرك النظرى
08.B Other	UNDERNEATH COVER PORTION DAMAGED	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.