CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934030
Transaction Date	04 Nov 2026, 14:27:28
Site Name	840 - Emirates Auctions
Transaction Number	18047439 (CC10009) (CC10011)



Vehicle Details

Chassis Number	WBAJB3A08K*******
Specification	GCC Specification
Make	BMW
Model	540
Model Year	2019
Color	Unknown
Mileage	93268 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	LEFT SIDE BOTH REPAINTED REPAIRED,FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION GETTING FADED	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	CENTER FLOOR COVERED	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	RELEASE HANDLE DAMAGED,REFITTED	غطاء المحرك
01.H Trunk	PORTION REPAIRED REPAINTED	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME BULK HEAD LEFT SIDE FENDER FRAM REPAIRED	وجود مؤشر لحادث في المقدمة
01.J Sign of back accident	BACK PANEL DENT QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف
01.K Vehicle Color	BLACK	لون المركبة
02 Chassis Condition		**الشاصي**
02.A Chassis	REAR RIGHT SIDE EXTENSION OUTER SLIGHTLY BEND,	الشاسيه
03 Engine Condition		**المحرك**
03.A Smoke	WHITE	دخان
03.B Engine Visual Condition	OIL WET PARTS REFITTED SHAKING, WIRING OPEN	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	DRIVER SEAT SIDE COVER LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS REFITTED MINOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Interior Condition		الحاله الداخليه
07.A AC Condition	OK	المكيف
07.B Power Window Switch And Glass	FRONT RIGHT SIDE NOT WORKING,LOCK SWITCH STUCK NOT WORKING	مفتاح النافذه و الزجاج
07.C Roof Ceiling	PORTION LOOSE	بطانه السقف
07.D Sun Visor	LEFT SIDE MIRROR DAMAGED	حاجب الشمس
07.E Door Panel	PORTION GETTING MELTED	لوحة بطانة الباب
07.F Gear Shifting Lever	KNOB GETTING WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae