



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	14 Aug 2022, 16:59:23
Transaction Number	54020751 (CC10008)	Queue Number	312309



Chassis Number	2T3BF4DV0CW263741
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	RAV 4
Model Year	2012
Color	Red
Mileage	142020 Miles
Fuel Type	Petrol
No. Of Cylinders	4
Specification	USA Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE PORTION REPAIRED,REPAINTED & BOTH REFITTED	مدكار
01.B Bonnet	REFITTED	غطاء المحرك
01.C Other	FRONT LEFT SIDE FENDER FRAME BULK HEAD , BACK PANEL REPAIRED	اخرى
01.D Floor	UNDER FLOOR FRONT COVER PORTION LOOSE	الارضية
01.E Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
01.F Sign of back accident		وجود مؤشر لحادث في الخلف
01.G Doors	FRONT LEFT SIDE & REAR RIGHT SIDE PORTION REPAIRED,REPAINTED & FRONT RIGHT SIDE PORTION REPAINTED	أبواب
01.H Pillars	LEFT SIDE PILLAR OUTER PANEL PORTION REPAIRED,REPAINTED	القوائم
02 Suspension System		ممتص الصدمات
02.A Other	STABLIZER LINK BOOT CUT	اخرى
02.B Arms	LOWER ARM BUSHES BUSHES CUT	ازرع
02.C Ball Joint	BOOT CUT	مفصل كروي

DEFECT	REMARKS	
03 Steering Condition		المقود
03.A Steering Boot	BOOT CUT	ربلة المقود
03.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2018/2019 CRACKED	الاطار الامامي
04.B Rear Tyre	LEFT SIDE 2018 CRACKED & RIGHT SIDE 2015 CRACKED , EXPIRED	الاطار الخلفي
05 Lights		الاضاءة
05.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
05.B Head Light	LENS FADED	الاضاءة الرئيسية
06 Brake Condition		الفرامل
06.A Brake Pedal	SPONGY	دواسة الفرامل
07 Transmission Condition		الجير
07.A Visual Gear Box Condition	MINOR OIL LEAK REFITTED	حالة الجير النظري
07.B Road Test	NOT CHECKED	فحص علي الطريق
07.C Propeller Shaft	REMOVED	ناقل الحركة
08 Chassis Condition		الشاصي
08.A Chassis	FRONT LEFT SIDE CHASSIS END INNER MINOR DENT	الشاسيه
09 Engine Condition		المحرك
09.A Visual Engine Condition	OIL LEAK REFITTED	حالة المحرك النظري
09.B Mount	MOUNT RUBBER CUT	كرسي
09.C Smoke	WHITE SMOKE	دخان
10 Interior Condition		الحاله الداخليه
10.A AC Condition	NOT COOLING	المكيف
10.B Air Bag	DAMAGED	وسائد هوائية
10.C Mirror	RIGHT SIDE ADJUSTMENT NOT WORKING PROPERLY & VIEW MIRROR MINOR FADED	المرايا
11 Seats Condition		المقاعد
11.A Seat Condition	SEATS HAVE EXTRA COVERS,COVER DAMAGED	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Car Check does not guarantee the vehicle's fitness for registration.