CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877818
Transaction Date	17 Oct 2026, 11:07:48
Site Name	840 - Emirates Auctions
Transaction Number	50116004 (CC10021) (CC10019)

Vehicle Details

Chassis Number	KNABA24376*******
Specification	GCC Specification
Make	Kia
Model	Picanto
Model Year	2006
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED ,MINOR DENTS SCRATCHES ,PORTION RUSTY PORTION FADED .	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS RUSTY	صدأ
01.C Floor	PORTION DENT	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED.	دعامية
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS MUDDY FRONT RIGHT SIDE PORTION DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECK PARTS REFITTED PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECK PARTS REFITTED GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE CRACKED DAMAGED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE CRACKED DAMAGED	الاطار الخلفي
06 Lights		الاضاءة

Condition	Remarks	الحالة
06.A Head Light	LENS FADED,ALL LIGHT NOT CHECKED .	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
09.B AC Condition	NOT CHECKED	المكيف
09.C Dash Board	PORTION CRACKED FADED	لوحة القياده
09.D Roof Ceiling	PORTION LOOSE	بطانه السقف
09.E Odometer reading	NOT CHECKED	قراءة عداد المسافات
09.F Door Panel	PORTION DAMAGED	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
10 Battery Condition		حالة البطارية
10.A Battery Condition	MISSING	حالة البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae