





Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18819287	Plate Category	: PRIVATE
Transaction Date	: 23 DEC 2019 11:28:26	Plate Number	: 0521 EA
Queue Number	: 127373	Import Doc. Ref.	:
Chassis Number	: MHFXX43G9B0030521	Manufacturer/Model	: TOYOTA/INOVA
Engine Number	:	Model Year	: 2011
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
01 Lights		الانوار
01.07 - Direction Indicators	CRACK	انوار مؤشرات ألتجاه
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.15 - Suspension Crack Or Bend, Bushes	SUSPENSION BUSHES CRACK	التوصيلات
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands	BRAKE ROTORS RUSTY	قوة فرامل المحور الامامي
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires	ALL TYRES DOT 2016 & CRACKS	الاطارات الامامية
04.07 - Rims	SCRATCHES	الرنجات
05 Body		الهيكل
05.02 - Paint	BODY SCRATCHES & DENTS / PORTIONS FADED	المصنع
05.08 - Chassis (Frame)	FRONT SIDE MEMBERS END DENT/ REPAIRED / RUSTY	الشاصية
06 General Items		الاشياء العامة
06.12 - Seats Condition And Seats Fixing	INTERIOR PARTLY WORN OUT	المقاعد وحالتها وثبيتها
06.14 - Transmission Condition	SHIFT SHOCK	حالة ناقل الحركة
06.16 - Engine Condition, Smoke	OIL LEAK	حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others	419111 KMS	ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة



Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18819287	Plate Category	: PRIVATE
Transaction Date	: 23 DEC 2019 11:28:26	Plate Number	: 0521 EA
Queue Number	: 127373	Import Doc. Ref.	:
Chassis Number	: MHFXX43G9B0030521	Manufacturer/Model	: TOYOTA/INOVA
Engine Number	:	Model Year	: 2011
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صدىغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only.		