



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	19 Jan 2023, 11:31:46
Transaction Number	71607532 (CC10010)	Queue Number	657755



Chassis Number	JN1CA31SX3T675999
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Maxima
Model Year	2003
Color	White
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	NOT CHECK	المكيف
01.B Dash Board	PORTION DAMAGED	لوحة القيادة
01.C Door Panel	PORTION MINOR DAMAGED	لوحة بطانة الباب
01.D Odometer reading	NOT CHECK	قراءة عداد المسافات
02 Body		جسم المركبة
02.A Rusty	UNDER BODY PARTS SUSPENSION FLOORING GETTING RUSTY	صدأ
02.B Sign of front accident		وجود مؤشر لحادث في المقدمة
02.C Paint	BODY TOTALLY REPAINTED , PORTION REPAIRED , MINOR DENT SCRATCHES,PORTION RUSTY	الصبغ
02.D Fenders	REFITTED	مدكار
02.E Bonnet	REFITTED	غطاء المحرك
02.F Floor	UNDER FLOOR GETTING RUSTY,PORTION WEAK HOLE,PORTION DENT	الارضية
02.G Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخرى
03 Suspension System		ممتص الصدمات

DEFECT	REMARKS	
03.A Arms	LOWER ARM BUSH CRACKED	ازرع
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Visual Gear Box Condition	NOT CHECK,OIL LEAK	حالة الجير النظرى
05 Seats Condition		المقاعد
05.A Seat Condition	EXTRA COVER	حالة المقاعد
06 Tires and Rims Condition		الاطارات
06.A Rear Tyre	BOTH SIDE 2020 CRACKED ,	الاطار الخلفي
06.B Front Tyre	BOTH SIDE 2020 CRACKED ,	الاطار الامامي
07 Engine Condition		المحرك
07.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,REFITTED OIL LEAK,OIL SUMP REPAIRED	حالة المحرك النظرى
08 Lights		الاضاءة
08.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
09 Chassis Condition		الشاصي
09.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED	الشاسيه
10 Steering Condition		المقود
10.A Steering Oil	OIL LEAK	زيت المقود
10.B Steering Boot	BOOT CUT	ربلة المقود
10.C Tie Rod End	BOOT CUT	مؤخرة الرودات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.