



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	31 Aug 2022, 11:43:57
Transaction Number	83458720 (CC10008)	Queue Number	312309



Chassis Number	SALLSAAD4DA771139
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Sport
Model Year	2013
Color	Brown
Mileage	75190 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2021 CRACKED	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
02 Wipers and Arms		المساحات
02.A Wiper Arm & Blade	WIPER TANK CAP MISSING	ازرع المساحات والشفرات
03 Interior Condition		الحاله الداخليه
03.A Roof Ceiling	PORTION LOOSE	بطانه السقف
03.B Sun Visor	PORTION DAMAGED	حاجب الشمس
03.C AC Condition	OK ,REAR LEFT SIDE GRILL DAMAGE	المكيف
04 Engine Condition		المحرك
04.A Visual Engine Condition	OIL LEAK , REFITTED	حالة المحرك النظري
05 Transmission Condition		الجير
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Visual Gear Box Condition	OIL LEAK & REFITTED	حالة الجير النظري
05.C DIFFERENTIAL	LEAK	الدفرنشيل

DEFECT	REMARKS	
06 Exhaust System		نظام العادم
06.A Modification	MODIFIED,NOISY.	تعديلات
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CRACKED.	أزرع
07.B Shock Absorber	REAR RIGHT SIDE DAMBER MISALIGN	ممتص الصدمات
07.C Suspension Subframe	SUB FRAME BRACKET DENT	
08 Body		جسم المركبة
08.A Fenders	REAR LEFT SIDE PORTION REPAIRED,REPAINTED	مدكار
08.B Trunk	NOT WORKING PROPERLY	صندوق
08.C Doors	FRONT LEFT SIDE REPAINTED	أبواب
08.D Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
09 Chassis Condition		الشاسي
09.A Chassis	BOTH SIDE MIDDLE CHASSIS PORTION DENT	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Transfer Certificate :	66844259
Chassis No :	SALLSAAD4DA771139
Vehicle Make :	RANGE ROVER
Vehicle Model :	SPORT
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Brown
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	75194 Kms. x
Previous Odometer Reading :	189736 Kms.
Origin : Great Britain	Model Year : 2013
Gear Type : Automatic	Engine Size : 5000 CC
Engine No : 12053122343...	Horse Power : 301
Axles No : 2	Cylinders : 8
No Of Doors : 4	No Of Seats : 5
G. V. W. : 2857 Kgs.	Empty Weight : 2122 Kgs.

Certificate Number :	5-TAS-2022-17571055		
Inspection Date :	06-09-2022		
Certificate Print Date :	06-09-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	14 min 26 sec		
Appointment Ref Number :	--		
Start Time :	15:19	End Time :	15:33
Lane :	01	Token No. :	199
Attempt :	1	Prints No. :	1

Carbon footprint



Take action to protect Dubai environment

Estimated Vehicle Consumption (Rate last 12 Months)

37749 KM	3885 L	12666 AED	9.3 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 16 %	Service brake imbalance on rear axle 3 %	Parking brake imbalance between LHS and RHS 25 %	Vehicle on Petrol CO Reading 0.42 %
Vehicle on Petrol HC Reading 112 PPM VOL			

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Odometer Device Odometer Reading Change	Authorized	Replaced	

Inspection Remarks: old km-189736 on 12/05/2022, minor engine oil leak, both side chassis lower portion minor dent.

Odometer Record

Replace Events Date 06/09/2022

Payment Details

Inspection Performed by 35063 2151 2151	Payment Method Cash	Transaction Number 17571055	Service Fees AED 170 Collected on 06/09/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Bajurdeen Abdul Gafoor

This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.