

Queue Number

2843799

Transaction Date

07 Oct 2026, 14:14:23

Site Name

840 - Emirates Auctions

Transaction Number

79151521 (CC10013) (CC10025)



Vehicle Details

Chassis Number	JN8AE2KP9B*****
Specification	Imported
Make	Nissan
Model	Quest
Model Year	2011
Color	Brown
Mileage	65825 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DENT RUSTY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Windshield	FRONT CRACK	زجاج
01.H Trunk	REPAINTED PORTION REPAIRED , AUTO NOT WORKING PROPERLY , REAR SWITCH MELTED	صندوق
01.I Vehicle Color	BLACK	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS PORTION GETTING RUSTY / CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Mount	MOUNT RUBBER CRACK	كرسي
03.B Engine Visual Condition	MINOR OIL LEAK , PARTS RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED EXTRA COVER , RIGHT SIDE ADJUSTMENT SWITCH PORTION LOOSE	حالة المقاعد
---------------------	--	--------------

Condition	Remarks	الحالة
05 Exhaust System		نظام العادم
05.A Other	CUT REWELDED	اخرى
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	MINOR JERKING , PARTS RUSTY	الحالة النظرية للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2022 CRACK	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2022 CRACK	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES , FRONT LEFT SIDE HUB COVER MISSING	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسية
08.B Brake Light	SWITCH DEFECTIVE	نور الفرامل
08.C Fog light	NOT WORKING	كشاف الضباب
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	REAR SIGN OF LEAK	ممتص الصدمات
09.B Arms	ARM BUSHES MINOR DRY CRACK	ازرع
09.C Ball Joint	BOOT CUT	مفصل كروي
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الروداد
11 Interior Condition		الحالة الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY (SIGN OF FLOODED)	اخرى
11.B Mirror	RIGHT SIDE PORTION LOOSE	المرآيا
11.C AC Condition	OK	المكيف
11.D Power Window Switch And Glass	REAR LEFT SIDE CURTAIN BRACKET DAMAGED	مفتاح النافذه و الزجاج
11.E Dash Board	CRACK MELTED , EXTRA COVER	لوحة القيادة
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Sunroof	NOT WORKING PROPERLY , FRONT MISALIGN	فتحت سقف
11.H Gear Shifting Lever	KNOB WORN OUT , LOCK COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص

only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae