





### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20220590	Plate Category	: PRIVATE
Transaction Date	: 12 JUL 2020 17:00:40	Plate Number	: 214302 EA
Queue Number	: 195300	Import Doc. Ref.	:
Chassis Number	: JTDBR22E573214302	Manufacturer/Model	: TOYOTA/COROLLA
Engine Number	:	Model Year	: 2007
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
01 Lights		الانوار
01.01 - Side Lights		الانوار الجانبية
	FENDER LIGHTS LENS BROKEN	
01.04 - Head Lights		الانوار الامامية
	LENS FADED	
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.04 - Steering Ball Joints, Boots		وصلات عمود عجلة القيادة
	NOISY UNDERNEATH WHEN RUNNING	
02.08 - Power Steering Pump		المضخة الهيدرولكية للمقود
	OIL LEAK	
02.13 - Stub Axle Assemblies, Boots		المحور
	AXLE RUBBER BOOT GREASE LEAK	
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
	DOT 2914 CRACKED	
04.07 - Rims		الرنجات
	COVER REMOVED	
05 Body		الهيكل
05.02 - Paint		الصبغ
	DENT/SCRATCHES/PORTION PEEL OFF	
05.03 - Doors		الابواب
	DOOR PORTION RUSTY & REAR LEFT DOOR PILLAR COVER REMOVED & RUBBER TORN	
05.05 - Bumpers		الدعامية
	FRONT & REAR BUMPER/CRASH BOX/BONNET.BULKHEAD REPAIRED	
05.07 - Floor		الارضية
	REAR COMPARTMENT/TRUNK DOOR & QUARTER PANEL REPAIRED/RUSTY	
05.08 - Chassis (Frame)		الشاصية
	REAR BOTH CHASSIS END REPAIRED	
05.10 - All Glasses		الزجاج الجانبي وزجاج الابواب
	REAR LEFT POWER WINDOW NOT WORKING	
06 General Items		الاشياء العامة
06.01 - Wiper Blades		ماسحات الزجاج الامامي
	WORNOUT	



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20220590	Plate Category	: PRIVATE
Transaction Date	: 12 JUL 2020 17:00:40	Plate Number	: 214302 EA
Queue Number	: 195300	Import Doc. Ref.	:
Chassis Number	: JTDBR22E573214302	Manufacturer/Model	: TOYOTA/COROLLA
Engine Number	:	Model Year	: 2007
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

06.14 - Transmission Condition	OIL LEAK	حالة ناقل الحركة
06.16 - Engine Condition, Smoke	OIL LEAK	حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others	61713 KM CAR WAS USED BY DRIVING SCHOOL	ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		يحتاج الى ميزانية العجلات
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
09.24 - Digital Display Damaged/Warning Lights	DASHBOARD GUAGE SLIGT FADED	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted	BODY PORTION REPAINTED	أثر صيغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.		