CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945000
Transaction Date	09 Nov 2026, 13:04:12
Site Name	840 - Emirates Auctions
Transaction Number	63653779 (CC10010) (CC10010)



Vehicle Details

Chassis Number	WDDUG8GB4K*******
Specification	Imported
Make	Mercedes
Model	S 63
Model Year	2019
Color	Black
Mileage	117213 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REFITTED LEFT SIDE REPAINTED, REAR LEFT SIDE QUARTER PANEL REPAINTED.	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED ,MINOR DNETS SCRATCHES .	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.E Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.F Bonnet	REPAINTED REFITTED . MODIFIED	غطاء المحرك
01.G Trunk	NOT CLOSSING	صندوق
01.H Sign of front accident	FRONT ASSEMBLY REFITTED .,	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS OCVERED NOT VISIBLE PROPERLY ,CHECKED ONLY VISIBLE AREA.	الشاسيه
02.B Other	SIGN ,OF ACCIDENT ,NEED TO REMOVE FENDER UNDER OCVER FOR INSPECTION /.	اخري
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY/OIL CAP DAMAGEDSIDE OCVER MISSING .	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
04.B Road Test	NOT CHECKED ..	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
05.C Rims Condition	MINOR DENTS SCRATCHES .	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	BODY LEVEL VERY LOW.	ممتص الصدمات
08.B Arms	BUSHES CRACKED.	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR ACCCESSORIES NOT CHECKED.	اخري
09.B AC Condition	NOT CHECKED.	المكيف
09.C FLoor Matting	CENTER CONSOLE BACK COVER LOOSE	فرش الأرضيه

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae