

Queue Number

2903393

Transaction Date

24 Oct 2026, 12:13:56

Site Name

840 - Emirates Auctions

Transaction Number

79578103 (CC10013) (CC10011)



Vehicle Details

Chassis Number

WA1AGDFE5F*****

Specification

GCC Specification

Make

Audi

Model

Q7

Model Year

2015

Color

White

Mileage

130216 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders

FRONT LEFT SIDE REFITTED

مدكار

01.B Paint

DENTS SCRATCHES ON BODY

الصبغ

01.C Rusty

UNDER FLOOR SUSPENSION PARTS GETTING RUSTY

صدأ

01.D Floor

UNDER FLOOR PORTION COVERED DIRTY MUDDY OILY

الارضية

01.E Bumper

MISALIGN, PORTION DAMAGED SCRATCHES, PART MISSING

دعامية

02 Chassis Condition

الشاسي

02.A Chassis

CHASSIS COVERED MUDDY DIRTY OILY CHECK VISIBLE AREA ONLY / OK

الشاسيه

03 Engine Condition

المحرك

03.A Engine Visual Condition

OIL LEAK DRIPPING DIRTY MUDDY REFITTED PARTS GETTING RUSTY

الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition

DRIVER SEAT BACK COVER DAMAGED MODIFIED

حالة المقاعد

05 Transmission Condition

الجير

05.A Gear Box Visual Condition

OIL LEAK DRIPPING , REFITTED , PARTS GETTING RUSTY OILY

الحالة النظرية للجير

05.B Road Test

NOT CHECKED

فحص علي الطريق

06 Tires and Rims Condition

الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2025,RIGHT 2024 CRACKED	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Suspension Subframe	MOUNT RUBBER DRY CRACK	ازرع
08.B Arms	ARM BUSHES MINOR DRY CRACK	
08.C Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحالة الداخليه
09.A Other	CENTER CONSOLE BOX,PANEL PORTION WORN OUT,COVER LOCK DAMAGED , INTERIOR PARTS GETTING RUSTY	اخرى
09.B Mirror	RIGHT SIDE ADJUSTMENT NOT WORKING PROPERLY	المرآيا
09.C AC Condition	OK, GRILL & SWITCH PORTION DAMAGED	المكيف
09.D Power Window Switch And Glass	FRONT BOTH SIDE SWITCH LOOSE & REAR BOTH SIDE QUARTER GLASS BEADING MELTED	مفتاح النافذه و الزجاج
09.E Roof Ceiling	LOOSE,PORTION CUT SCRATCHES	بطانه السقف
09.F Door Panel	PORTION GETTING WORN OUT,CIGARETTE ASHTRAY DAMAGED	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.H Sunroof	REAR CURTAIN LOCK NOT WORKING	فتحت سقف
09.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
09.J Engine Start Button	GETTING WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae