



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	14 Sep 2021, 14:55:59
Transaction Number	94809450 (CC10006)	Queue Number	312309



Chassis Number	JN8AY2NY4F9117273
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2014
Color	--
Mileage	197954

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REAR RIGHT SIDE REPAIRED, REPAINTED & LEFT SIDE BOTH, FRONT RIGHT SIDE REPAINTED	مدكار
01.B Paint	PORTION REPAIRED , REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Doors	RIGHT SIDE BOTH DOOR, TRUNK REPAIRED, REPAINTED & LEFT SIDE BOTH REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS, CHASSIS FRAME GETTING RUSTY	صدأ
01.E Floor	RIGHT SIDE RUNNING BOARD OUTER PANEL REPAIRED & REAR RIGHT SIDE FENDER COVER DAMAGED	الارضية
01.F Bumper	REPAINTED & MISALIGN	دعامية
01.G Roof	REPAINTED	السقف
01.H Bonnet	REPAINTED , SHOCK WEAK & REAR TRUNK SHOCK WEAK & RUSTY	غطاء المحرك
01.I Other	FRONT RIGHT SIDE FRANDER FRAME, BRACKET REPAIRED	اخرى
01.J Pillars	D/PILLAR GETTING RUSTY	القوائم
02 Chassis Condition		الشاسيه
02.A Chassis	CHASSIS FRAME GETTING RUSTY	الشاسيه
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED	كرسي
03.B Other	OK	اخرى

DEFECT	REMARKS	
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Transmission Condition		الجير
05.A Gear Box	OK	الجير
05.B Gear Box Mount	BUSHES CRACKED	كرسي الجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020 WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020 WORN OUT	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Other	WORN OUT	اخرى
08 Lights		الاضاءة
08.A Head Light	LENS SLIGHTLY FADED	الاضاءة الرئيسية
08.B Other	OK	اخرى
09 Brake Condition		الفرامل
09.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
10 Suspension System		ممتص الصدمات
10.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED	ازرع
10.B Shock Absorber	WEAK & LEAK , RUSTY	ممتص الصدمات
11 Steering Condition		المقود
11.A Tie Rod End	BUSHES CRACKED	مؤخرة الرودادات
11.B Axel	BOOT CUT & LEAKING	اكسلات
11.C Steering Boot	BOOT CUT & LEAKING	ربلة المقود
12 Interior Condition		الاجزاء الداخلية
12.A Other	OK	اخرى
12.B Mirror	OK	المرايا
12.C AC Condition	A/C NOT COOLING	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

