

Queue Number	2627812	Transaction Date	08 Aug 2026, 11:55:03
Site Name	840 - Emirates Auctions	Transaction Number	96437958 (CC10013) (CC10019)



Vehicle Details

Chassis Number	LGWFF8A60J*****
Specification	GCC Specification
Make	Haval
Model	H9
Model Year	2018
Color	White
Mileage	154554 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE & REAR LEFT SIDE REPAINTED, PORTION REPAIRED,	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES,	الصبغ
01.C Rusty	UNDER BODY PARTS, SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR MUDDY, PORTION DENTS	الارضية
01.E Bumper	MISALIGN,PORTION CRACKED	دعامية
01.F Trunk	NOT CHECK	صندوق
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS FRAME DIRTY MUDDY PORTION GETTING RUSTY	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
04 Exhaust System		نظام العادم
04.A Other	DENT	اخرى
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
05.B Propeller Shaft	FRONT MISSING	ناقل الحركة

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACKED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	ARM BUSHES RDY CRACK	ازرع
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY,	اخرى
09.B AC Condition	NOT CHECKED	المكيف
09.C Roof Ceiling	PORTION LOOSE	بطانة السقف
09.D Door Panel	PORTION DAMAGED,LOOSE	لوحة بطانة الباب

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae