CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899756
Transaction Date	24 Oct 2026, 11:33:55
Site Name	840 - Emirates Auctions
Transaction Number	60633833 (CC10010) (CC10010)



Vehicle Details

Chassis Number	5TDKK4CC7A*******
Specification	Imported
Make	Toyota
Model	Sienna
Model Year	2010
Color	Silver
Mileage	230943 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REFITTED .	مدكار
01.B Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.E Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.F Bonnet	REFITTED .	غطاء المحرك
01.G Door Handle &Lock	REAR OUTER HANDLE BROKEN	مقابض الأبواب والأقفال
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT CHASISS END REPAIRED DENT ,REAR EXTENSION END REPAIRED DENT ,GETTING RUSTY.	الشاسيه
02.B Chassis Number	VIN CHECKED ONLY STICKER.	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Mount	BUSHES CRACKED .	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY,ELECTRICAL FAULTY.	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY LOOSE PORTION DAMAGED.	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظره للجير
05.B Gear Box Mount	BUSHES CRACKED.	كرسي الجير
05.C Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRCKED WORN OUT .	الاطار الخلفي
06.C Rims Condition	RUSTY	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK,BRACKET DAMAGED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	BUSHES CUT	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
10.C Axle	BOOT CUT	اكسلات
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B Mirror	LOOSE PORTION FADED.	المرايا
11.C AC Condition	NOT CHECKED.	المكيف
11.D Dash Board	PORTION LOOSE .	لوحة القياده
11.E Roof Ceiling	PORTION LOOSE	بطانه السقف
11.F Sun Visor	LOOSE	حاجب الشمس
11.G Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر wecare@carscheck.ae