

Queue Number 2815073

Transaction Date 29 Sep 2026, 16:41:08

Site Name
840 - Emirates AuctionsTransaction Number
80852787 (CC10009) (CC10012)

Vehicle Details

Chassis Number	1C4BJWAG9D*****
Specification	GCC Specification
Make	Jeep
Model	Wrangler
Model Year	2013
Color	Black
Mileage	215368 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION RUSTY , (BODY KIT MODIFIED)	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS THICK RUST PROOFED, MUDDY COVERED	الارضية
01.F Bumper	MODIFIED	دعامية
01.G Windshield	REAR SHOCK WEAK NOT WORKING	زجاج
01.H Bonnet	REFITTED	غطاء المحرك
01.I Trunk	REFITTED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY THICK RUST PROOFED REPAINTED PORTION RUSTY	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK OPEN REFITTED GETTING RUSTY REPAINTED	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	EXTRA COVER	حالة المقاعد
---------------------	-------------	--------------

05 Exhaust System

نظام العادم

Condition	Remarks	الحالة
05.A Other	CUT REWELDED	اخرى
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	REFITTED GETTING RUST REPAINTED	الحالة النظرية للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
06.C Clutch	MODIFIED	القابض
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
07.C Rims Condition	HUB COVER MISSING	حالة الجنوط
08 Lights		الاضاءة
08.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08.B Fog light	NOT WORKING	كشاف الضباب
09 Brake Condition		الفرامل
09.A Hand Brake	NOT WORKING	فرامل اليد
10 Suspension System		ممتص الصدمات
10.A Arms	BUSHES CRACKED	ازرع
11 Interior Condition		الحالة الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED , INTERIOR MODIFIED	اخرى
11.B AC Condition	OK	المكيف
11.C Floor Matting	EXTRA COVER	فرش الأرضيه
11.D Sun Visor	BOTH SIDE MIRROR COVER MISSING	حاجب الشمس
11.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.F Engine Start Button	KEY PORTION DAMAGED	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae