

Queue Number

2877731

Transaction Date

19 Oct 2026, 17:42:16

Site Name

840 - Emirates Auctions

Transaction Number

53804227 (CC10026) (CC10026)



Vehicle Details

Chassis Number	WAUSGC4G0B*****
Specification	GCC Specification
Make	Audi
Model	A7
Model Year	2011
Color	Grey
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.E Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.F Bonnet	REPAINTED , STAY SHOCK WEAK NOT WORKING , MISALIGN	غطاء المحرك
01.G Trunk	REPAINTED PORTION REPAIRED , MISALIGN	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS GETTING RUSTY , OILLY MUDDY	الشاسيه
--------------	-------------------------------------	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED , PARTS REFITTED MINOR OIL LEAK . PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
---------------------	------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	NOT CHECKED PARTS REFITTED GETTING RUSTY , MUDDY OILLY	الحالة النظرية للجير
--------------------------------	--	----------------------

Condition	Remarks	الحالة
05.B Gear Box Mount	NOT CHECKED, PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET , MUDDY	كرسي الجير
05.C Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 WORN OUT & CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED PORTION DAMAGE , ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CRACK	مؤخرة الرودادات
10 Interior Condition		الحالة الداخليه
10.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	NOT CHECK	المكيف
10.C Dash Board	PORTION WORN OUT	لوحة القيادة
10.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
10.E Odometer reading	NOT CHECK	قراءة عداد المسافات
10.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	PORTION WORN OUT , DUST COVER DAMAGE	ذراع نقل السرعات
10.H Engine Start Button	REMOTE PORTION WORN OUT	زر تشغيل المحرك
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae