CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2966519
Transaction Date	10 Nov 2026, 13:49:45
Site Name	840 - Emirates Auctions
Transaction Number	67134827 (CC10008) (CC10011)



Vehicle Details

Chassis Number	JN8AY2NYXF*******
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2015
Color	White
Mileage	140288 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAIRED REPAINTED,MINOR DENTS SCRATCHES,PORTION GETTING RUSTY(BODY SHAPE CHANGE OLD TO NEW MODEL)	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN PORTION DAMAGED.FRONT BUMPER FRAME MISSING	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Pillars	LEFT SIDE C/PILLAR OUTER PANEL REPAINTED PORTION REPAIRED	القوائم
01.H Trunk	REFITTED,REAR SWITCH AUTO NOT WORKING CHROME STRIP LOOSE	صندوق
01.I Sign of front accident	FENDER FRAME ,RADIATOR SUPPORT ,BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT LEFT SIDE CHASSIS AT LOADING POINT REPAIRED	الشاسيه
03 Engine Condition		**المحرك**
03.A Other	ENGINE COMPARTMENT HAVE EXTRA ELECTRIC WIRE MODIFIED ,CUT	اخري
03.B Engine Visual Condition	MINOR OIL LEAK ,REFITTED ,ABNORMAL NOISY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	BACK COVER PORTION LOOSE CUT & DRIVER SEAT LOOSE	حالة المقاعد

Condition	Remarks	الحالة
05 Exhaust System		نظام العادم
05.A Catalytic Converter	MISSING	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	OIL LEAK ,REFITTED	الحالة النظريه للجير
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025 WORN OUT	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2025 WORN OUT	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	LEFT SIDE DAMAGED REPAIRED,PORTION CRACK	الاضاءة الرئيسية
08.B Tail Light	FADED	الضوء الخلفي
08.C Warning Light	SOME WARNING LIGHT HIDDEN	ضوء تحذير
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY,COOL BOX COVER LEATHER PORTION WORN OUT,INTERIOR PORTION REFITTED MODIFIED & REAR CUP HOLDER DAMAGED	اخري
09.B Mirror	LEFT SIDE LOOSE AUTO FOLDING NOT WORKING,BOTH SIDE COVER FADED	المرايا
09.C AC Condition	FRONT OK,REAR NO COOLING	المكيف
09.D Dash Board	PORTION MELTED WORN OUT,LEATHER PORTION REFITTED	لوحة القياده
09.E Roof Ceiling	PORTION DIRTY	بطانه السقف
09.F Door Panel	FRONT LEFT SIDE HANDLE PORTION LOOSE	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	KNOB WORN OUT,SHIFT LOCK COVER MISSING	ذراع نقل السرعات
09.I Engine Start Button	WORN OUT	زر تشغيل المحرك
10 Engine Cooling System		نظام تبريد المحرك
10.A Radiator Cooling Fan	WIRE LOOSE ,UPPER COVER DAMAGED	مروحة تبريد المبرد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae