



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **09 Dec 2024, 23:06:15**
 Transaction Number **57078142 (CC10018) (CC10018)** Queue Number **1192808**



Chassis Number **LGWCA2199CC637577**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Great Wall**
 Model **Pickup**
 Model Year **2012**
 Color **White**
 Mileage **N/A Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED,, DENTS, SCRATCHES ON BODY, PORTION FADED, PORTION RUSTY	الصبغ
01.B Floor	UNDER BODY PARTS, SUSPENSION, FLOOR, CHASSIS NOT CHECK	الارضية
01.C Bumper	MISALIGN ,PORTION DAMAGED	دعامية
01.D Windshield	FRONT CRACKED	زجاج
01.E Roof	RUSTY,HOLE WEAK	السقف
01.F Bonnet	RUSTY,HOLE WEAK	غطاء المحرك
01.G Pillars	LEFT SIDE A/ PILLAR RUSTY	القوائم
01.H Other	VISUAL TEST ONLY, SIGN OF WATER FLOOD	اخرى
02 Chassis Condition		الشاسي
02.A Chassis	NOT CHECKED	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START , ALL SYSTEM NOT CHECK	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION DAMAGED	حالة المقاعد

DEFECT	REMARKS	
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	CRACKED DAMAGED	الاطار الامامي
06.B Rear Tyre	CRACKED DAMAGED	الاطار الخلفي
06.C Rims Condition	MINOR DENTS, SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	BOTH SIDE COVER CRACKED & LENS FADED , ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
09 Interior Condition		الحالة الداخلية
09.A AC Condition	NOT CHECKED	المكيف
09.B Dash Board	PORTION DAMAGED	لوحة القيادة
09.C Odometer reading	NOT CHECKED	قراءة عداد المسافات
09.D Door Panel	PORTION CRACKED	لوحة بطانة الباب
09.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10 Battery Condition		حالة البطارية
10.A Battery Condition	MISSING	حالة البطارية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.
- For complaints and inquiries reach out to us on wecare@carscheck.ae



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.
- للاشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae