

Queue Number 2707050

Transaction Date 02 Sep 2026, 12:26:33

Site Name
840 - Emirates AuctionsTransaction Number
67446683 (CC10021) (CC10011)

Vehicle Details

Chassis Number	WDDHF3EB4E*****
Specification	GCC Specification
Make	Mercedes
Model	E200
Model Year	2014
Color	Black
Mileage	128354 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE REFITTED,REAR LEFT REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Bumper	MISALIGN	دعامية
01.E Bonnet	REPAIRED REPAINTED REFITTED,SHOCK WEAK	غطاء المحرك
01.F Trunk	PORTION REPAIRED REPAINTED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COOVERED,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED,PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT ADJUSTMENT NOT WORKING	حالة المقاعد
---------------------	------------------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	REFITTED,PARTS GETTING RUSTY,MINOR OIL LEAK,MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE PORTION DAMAGED	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Interior Condition		الحالة الداخلية
08.A Other	CENTER CONSOLE BOX COVER,SLIDING COVER PORTION DAMAGED CRACK	اخرى
08.B AC Condition	OK,GRILL PORTION LOOSE,SWITCH PORTION FADED	المكيف
08.C Power Window Switch And Glass	MAIN SWITCH PANEL LOOSE,BOTH SIDE CURTAIN NOT VISIBLE	مفتاح النافذه و الزجاج
08.D Audio	SCREEN PORTION DAMAGED	صوتيات
08.E Roof Ceiling	PORTION LOOSE	بطانه السقف
08.F Door Panel	PORTION LOOSE	لوحة بطانة الباب
08.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae