



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	06 Jan 2022, 18:09:16
Transaction Number	53441098 (CC10006)	Queue Number	312309



Chassis Number	2C3CDXBG2FH729999
Engine Number	
Vehicle Class	Car
Manufacturer	Dodge
Model	Charger
Model Year	2015
Color	Black
Mileage	109777 Miles
Fuel Type	Petrol
No. Of Cylinders	6
Specification	USA Imported

DEFECT	REMARKS	
01 Seats Condition		المقاعد
01.A Seat Condition	OK	حالة المقاعد
02 Interior Condition		الحالة الداخلية
02.A Mirror	OK	المرابيا
02.B Door Panel	LEFT SIDE PORTION CRACKED & LOOSE	لوحة بطانة الباب
02.C Steering Wheel and control buttons	COVER PORTION DAMAGED	عجلة القيادة وازرار التحكم
03 Lights		الاضاءة
03.A Tail Light	OK	الانارة
03.B Head Light	OK	الاضاءة الرئيسية
04 Wipers and Arms		المساحات
04.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2017/2018	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2017/2018	الاطار الخلفي
06 Body		جسم المركبة

DEFECT	REMARKS	
06.A Fenders	LEFT SIDE BOTH PORTION REPAIRED, REPAINTED & FRONT RIGHT SIDE REPAINTED, REFITTED	مدكار
06.B Doors	LEFT SIDE REAR PORTION REPAIRED, REPAINTED, FRONT REPAINTED & FRONT RIGHT SIDE REPLACED	أبواب
06.C Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخرى
06.D Bumper	REPAINTED	دعامية
06.E Bonnet	REPAINTED & REFITTED	غطاء المحرك
06.F Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
06.G Windshield	FRONT SPOT CRACKED	زجاج
06.H Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
07 Chassis Condition		الشاصي
07.A Chassis	VISABLE AREA OK	الشاسيه
08 Transmission Condition		الجير
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Gear Box	OK	الجير
09 Engine Condition		المحرك
09.A Engine Condition	OIL LEAK	حالة المحرك
10 Exhaust System		نظام العادم
10.A Modification	REAR MUFFILER MISSING	تعديلات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.