CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3007453
Transaction Date	18 Nov 2026, 16:43:26
Site Name	840 - Emirates Auctions
Transaction Number	71208335 (CC10013) (CC10011)



Vehicle Details

Chassis Number	5N1AL0MM5G*******
Specification	GCC Specification
Make	Infiniti
Model	QX60
Model Year	2016
Color	White
Mileage	214280 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAINTED,MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION MINOR DENT	الارضية
01.E Bumper	MISALIGN,PORTION CRACK	دعامية
01.F Bonnet	REFITTED,SHOCK WEAK,RIGHT SIDE SHOCK DAMAGED	غطاء المحرك
01.G Trunk	REFITTED,REAR SWITCH DAMAGED NOT WORKING	صندوق
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS PORTION RUST PROOFED GETTING RUSTY / CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Chassis Number	VIN AREA GETTING RUSTY	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	REFITTED , MINOR OIL LEAK , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	MINOR JERKING , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06 Lights		الاضاءة
06.A Tail Light	LEFT SIDE PORTION CRACK	الضوء الخلفي
06.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	ARM BUSHES DRY CRACK	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
07.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودات
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE BOX COVER PORTION DAMAGED / INTERIOR PARTS RUSTY WATER FLOODED	اخري
09.B AC Condition	OK,GRILL PORTION DAMAGED	المكيف
09.C Dash Board	PORTION WORN OUT	لوحة القياده
09.D Steering Wheel and control buttons	ADJUSTMENT NOT WORKING	عجلة القيادة وازرار التحكم
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	WATER LEVEL LOW	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae