

Queue Number 2539425

Transaction Date 15 Jul 2026, 14:12:13

Site Name
840 - Emirates AuctionsTransaction Number
37177440 (CC10006) (CC10019)

Vehicle Details

Chassis Number	WDDWF4CB9J*****
Specification	GCC Specification
Make	Mercedes
Model	C200
Model Year	2018
Color	White
Mileage	210893 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REPAINTED, PORTION REPAIRED, FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS, SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COMPLETELY COVERED, PORTION RUSTY, COVER PORTION DAMAGED	الارضية
01.E Bumper	MISALIGN, COVER HOOK MISSING	دعامية
01.F Bonnet	REPAINTED, PORTION REPAIRED, REFITTED & SHOCK WEAK	غطاء المحرك
01.G Trunk	MISALIGN	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED, CHECKED VISIBLE AREA ONLY	الشاسيه
02.B Other	FOR FULL INSPECTION NEED TO REMOVE FRONT BOTH SIDE FENDER, UNDER ENGINE, FLOOR COVER	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	SHAKING, OVERHEAT, OIL WET, PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT COVER PORTION WORN OUT	حالة المقاعد
---------------------	------------------------------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	JERKING, OIL WET, PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2024 CRACKED & RIGHT SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Interior Condition		الحالة الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY,	اخرى
08.B AC Condition	NOT COOLING	المكيف
08.C Power Window Switch And Glass	FRONT BOTH SIDE & REAR LEFT SIDE SWITCH BUTTON DAMAGED,MISSING	مفتاح النافذه و الزجاج
08.D Roof Ceiling	PORTION LOOSE	بطانه السقف
08.E Sun Visor	LEFT SIDE COVER MIRROR LOOSE & LIGHT NOT WORKING	حاجب الشمس
08.F Steering Wheel and control buttons	WORN OUT & SWITCH FADED	عجلة القيادة وازرار التحكم
08.G Sunroof	NOT WORKING PROPERLY	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae