

Queue Number

2729916

Transaction Date

10 Sep 2026, 13:46:30

Site Name

840 - Emirates Auctions

Transaction Number

81934393 (CC10009) (CC10012)



Vehicle Details

Chassis Number	1GNKV9ED8B*****
Specification	GCC Specification
Make	Chevrolet
Model	Traverse
Model Year	2011
Color	White
Mileage	284148 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصيغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Bonnet	REFITTED , SHOCK WEAK NOT WORK	غطاء المحرك
01.D Pillars	REAR LEFT SIDE ROCKER PANEL REPAIRED	القوائم

02 Chassis Condition

الشاسي

02.A Chassis	PORTION COVERED MUDDY CHECKED VISIBLE AREA OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK REFITTED PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---------------------------------------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	REFITTED ,OIL WET PARTS GETTING RUSTY,DELAY SHIFTING	الحالة النظرية للجير
04.B DIFFERENTIAL	REAR OIL WET	الدفرنشل
04.C Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2022	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي

Condition	Remarks	الحالة
06 Wipers and Arms		المساحات
06.A Wiper Arm &Blade	REAR BLADE MISSING	ازرع المساحات والشفرات
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PRTS GETTING RUSTY	اخرى
08.B AC Condition	OK	المكيف
08.C Audio	BUTTON FADED	صوتيات
08.D Dash Board	LOCK COVER LOOSE	لوحة القيادة
08.E Sun Visor	LEFT SIDE MIRROR COVER LOOSE , MIRROR CRACK , RIGHT SIDE COVER MISSING	حاجب الشمس
08.F Door Panel	PORTION CRACK	لوحة بطانة الباب
08.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae