CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2954172
Transaction Date	13 Nov 2026, 15:08:49
Site Name	840 - Emirates Auctions
Transaction Number	51885978 (CC10021) (CC10021)



Vehicle Details

Chassis Number	6G1EL54B17*******
Specification	GCC Specification
Make	Chevrolet
Model	Lumina
Model Year	2007
Color	Black
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED	دعامية
01.E Bonnet	CHROME MISSING	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED,MUDDY PORTION DENT,CHECKED VISIBLE AREA ONLY	الشاسيه
03 Engine Condition		المحرك
03.A Mount	CUT	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED,REAR SEAT MISSING	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Modification	MODIFIED	تعديلات
06 Transmission Condition		الجير

Condition	Remarks	الحالة
06.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
07.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	BODY LEVEL LOW	ممتص الصدمات
10.B Arms	BUSHES CRACK	ازرع
10.C Ball Joint	BOOT CUT	مفصل كروي
10.D Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOX DAMAGED,INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
11.B AC Condition	NOT CHECK	المكيف
11.C Dash Board	PORTION DAMAGED	لوحة القياده
11.D Roof Ceiling	PORTION DAMAGED	بطانه السقف
11.E Door Panel	PORTION DAMAGED	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.