



Test Certificate

| | | | |
|---------------------|--------------------------|--------------------|-----------|
| Site Number | : 840-TASJEEL EM AUCTION | Plate Code | : 0 |
| Transaction Number | : 18502718 | Plate Category | : PRIVATE |
| Transaction Date | : 11 NOV 2019 11:59:56 | Plate Number | : 0983 EA |
| Queue Number | : 117762 | Import Doc. Ref. | : |
| Chassis Number | : WAUAYJFF6F1010983 | Manufacturer/Model | : AUDI/A3 |
| Engine Number | : | Model Year | : 2015 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : WHITE |
| Service / Indicator | : DSC AUCTION | | |

Statement of Vehicle Condition

| Defect | Result | Remarks |
|-------------------------------------|--------|----------------------------------|
| AUTOMATIC TEST: | | |
| 13 Brake System | | الفرامل |
| 13.04 - Brake Test | Passed | فحص الفرامل |
| 14 Exhaust Gas Test | | الغاز العادم والكربون |
| 14.01 - Exhaust Gas Test | Passed | فحص الغاز العادم-الكربون |
| VISUAL TEST: | | |
| 02 Steering And Suspension System | | عجلة القيادة ونظام التوصيلات |
| 02.13 - Stub Axle Assemblies, Boots | | المحور |
| | | FRONT LEFT AXLE BOOT GREASE LEAK |
| 05 Body | | الهيكل |
| 05.03 - Doors | | الابواب |
| | | BODY PORTION SCRATCH |
| 06 General Items | | الاشياء العامة |
| 06.14 - Transmission Condition | OK | حالة ناقل الحركة |
| 06.16 - Engine Condition, Smoke | OK | حالة المحرك - الدخان |
| 07 Remarks | | ملاحظات |
| 07.04 - Others | | ملاحظات اخرى |
| | | 201964 KM. |
| 09 Auction | | الفحص الكامل |
| 09.06 - Chassis Ok | | الشاصي جيد |
| 09.14 - Sign Of Front Accident | | أثر حادث في مقدمة المركبة |
| 09.25 - Body Repainted | | أثر صبغ في المركبة |
| | | BODY PORTION REPAINTED |

The Test Certificate Shows the test Result at the time of inspection only.