CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877808
Transaction Date	17 Oct 2026, 11:07:52
Site Name	840 - Emirates Auctions
Transaction Number	14432851 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JN1BDAB14Z*******
Specification	GCC Specification
Make	Nissan
Model	Sunny
Model Year	1996
Color	White
Mileage	629409 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENT .	الارضية
01.D Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.E Pillars	DOOR POST ROCKER PANEL RUNNING BOARD REPAIRED.	القوائم
01.F Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ,FENDER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة
01.G Sign of back accident	BACK PANEL ,QUARTER PANEL ,SPARE WHEEL HOUSING REPAIRED,DENT .	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASSIS ,REAR EXTENSION END REPAIRED DENT .	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق
05 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2024 CRACKED WORN OUT .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024 CRACKED WORN OUT .	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	BUSHES CUT.	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT.	ربلة المقود
09.B Steering Box	OIL LEAK	جهاز المقود
09.C Axle	BOOT CUT.	اكسلات
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخري
10.B Mirror	LOOSE.	المرايا
10.C Dash Board	LOOSE PORTION CUT .	لوحة القياده
10.D Roof Ceiling	PORTION LOOSE.	بطانه السقف
10.E Sun Visor	LOOSE	حاجب الشمس
10.F Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
10.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae