



## TEST CERTIFICATE

|                    |                              |                  |                              |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number        | <b>840-Emirates Auctions</b> | Transaction Date | <b>17 May 2022, 17:56:53</b> |
| Transaction Number | <b>25551556 (CC10006)</b>    | Queue Number     | <b>312309</b>                |



|                  |                          |
|------------------|--------------------------|
| Chassis Number   | <b>SALGS3TF3FA198871</b> |
| Engine Number    |                          |
| Vehicle Class    | <b>Car</b>               |
| Manufacturer     | <b>Range Rover</b>       |
| Model            | <b>Vogue</b>             |
| Model Year       | <b>2015</b>              |
| Color            | <b>Grey</b>              |
| Mileage          | <b>143409 Km</b>         |
| Fuel Type        | <b>Petrol</b>            |
| No. Of Cylinders | <b>8</b>                 |
| Specification    | <b>USA Imported</b>      |

| DEFECT                           | REMARKS  |                          |
|----------------------------------|--|--------------------------|
| <b>01 Transmission Condition</b> |  | <b>الجير</b>             |
| 01.A Road Test                   | NOT CHECK  | فحص علي الطريق           |
| 01.B Visual Gear Box Condition   | SIGN OF LEAK   | حالة الجير النظرى        |
| <b>02 Body</b>                   |  | <b>جسم المركبة</b>       |
| 02.A Doors                       | PORTION REPAIRED, REPAINTED  | أبواب                    |
| 02.B Paint                       | BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES                       | الصبغ                    |
| 02.C Fenders                     | FRONT BOTH SIDE REPAINTED , REFITTED & REAR RIGHT SIDE PORTION REPAIRED, REPAINTED | مدكار                    |
| 02.D Fuel Tank                   | DENT & RUSTY   | خزان الوقود              |
| 02.E Sign of back accident       |  | وجود مؤشر لحادث في الخلف |
| 02.F Other                       | BACK PANEL RIGHT SIDE QUARTER PANEL REPAIRED                                       | اخري                     |
| 02.G Bumper                      | FRONT BUMPER ASSEMBLY RFITTED  | دعامية                   |
| 02.H Rusty                       | UNDER BODY PARTS RUSTY   | صدأ                      |
| 02.I Floor                       | FLOOR COVERED  | الارضية                  |
| <b>03 Engine Condition</b>       |  | <b>المحرك</b>            |
| 03.A Visual Engine Condition     | SIGN OF MINOR OIL LEAK   | حالة المحرك النظرى       |

| DEFECT                             | REMARKS                            |                        |
|------------------------------------|------------------------------------|------------------------|
| <b>04 Suspension System</b>        |                                    | <b>ممتص الصدمات</b>    |
| 04.A Arms                          | LOWER ARM BUSHES CRACKED           | ازرع                   |
| <b>05 Interior Condition</b>       |                                    | <b>الحاله الداخليه</b> |
| 05.A AC Condition                  | OK                                 | المكيف                 |
| 05.B Power Window Switch           | REAR LEFT SIDE CURTAIN NOT WORKING | مفتاح النافذه          |
| <b>06 Tires and Rims Condition</b> |                                    | <b>الاطارات</b>        |
| 06.A Front Tyre                    | BOTH SIDE 2021                     | الاطار الامامي         |
| 06.B Rear Tyre                     | BOTH SIDE 2021                     | الاطار الخلفي          |
| <b>07 Chassis Condition</b>        |                                    | <b>الشاصي</b>          |
| 07.A Chassis                       | CHACKED VISIBLE AREA OK            | الشاسيه                |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.