

TEST CERTIFICATE

Site Number
Transaction Number

840-Emirates Auctions 27207322 (CC10006) Transaction Date

30 Nov 2021, 17:48:42

Queue Number

312309



Chassis Number **3FA6P0HD1HR293387**

Engine Number

Vehicle Class Car

Manufacturer Ford

Model Fusion

Model Year 2017

Color Red

Mileage 51228 Miles

Fuel Type

Petrol

No. Of Cylinders

Specification USA Imported

DEFECT REMARKS

01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, BODY MINOR DENT, SCRATCHES	الصبغ
01.B Fenders	FRONT RIGHT SIDE FENDER REPAINTED, PORTION REPAIRED	مدكار
01.C Doors	FRONT LEFT SIDE REPAINTED, PORTION REPAIRED	أبواب
01.D Bonnet	REPAINTED, PORTION REPAIRED	غطاء المحرك
01.E Bumper	REPAINTED & MISALIGN	دعامية
01.F Pillars	LEFT OUTER A/ PILLAR PORTION REPAINTED	القوائم
01.G Floor	UNDER FLOOR COVERD	الارضية
01.H Rusty	UNDER BODY PARTS , SUSPENTION & REAR BUMPER FRAME GETTING RUSTY	صدأ
02 Interior Condition		الحاله الداخليه
02.A AC Condition	ОК	المكيف
02.B Dash Board	DASHBAORD LEATHER LOOSED	لوحة القياده
03 Seats Condition		المقاعد
03.A Seat Belt	ОК	حزام الأمان
03.B Seat Condition	LEATHER CRACKED	حالة المقاعد

DEFECT	REMARKS	
04 Wipers and Arms		المساحات
04.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
05 Lights		الاضاءة
05.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
05.B Head Light	BOTH SIDE BRACKET BROCKEN	الاضاءة الرئيسية
05.C Other	ОК	اخري
06 Chassis Condition		الشاصي
06.A Chassis	VISABLE AREA OK	الشاسيه
07 Transmission Condition		الجير
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Gear Box	ОК	الجير
08 Tires and Rims Condition		الاطارات
08.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2016 CRACKED, EXPIRED	الاطار الخلفي
09 Engine Condition		المحرك
09.A Other	UNDER ENGINE COVER	اخری

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.