



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	24 May 2023, 10:20:04
Transaction Number	60623037 (CC10008)	Queue Number	724824



Chassis Number	KMJWA37R2CU336169
Engine Number	
Vehicle Class	Car
Manufacturer	Hyundai
Model	H1
Model Year	2012
Color	White
Mileage	388210 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Propeller Shaft	CENTER BEARNING RUBBER WORN OUT	ناقل الحركة
01.C Gear Box Mount	MOUNT BUSHES CRACKED	كرسي الجير
01.D Visual Gear Box Condition	REFITTED,JERKING	حالة الجير النظرى
02 Body		جسم المركبة
02.A Bumper	MISALIGN,PORTION DAMAGED	دعامية
02.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
02.C Door Handle &Lock	REAR LEFT SIDE OUTER HANDLE DAMAGED	مقابض الأبواب والأقفال
02.D Sign of back accident		وجود مؤشر لحادث في الخلف
02.E Trunk	REPAIRED,REPAINTED,REFITTED	صندوق
02.F Fenders	REAR BOTH SIDE PORTION REPAIRED,REPAINTED	مدكار
02.G Pillars	RIGHT SIDE C/PILLAR INNER COVER MISSING	القوائم
02.H Floor	FLOOR,RUNNING BOARD DENT	الارضية
02.I Doors	PORTION REPAINTED,PORTION REPAIRED	أبواب
02.J Fuel Tank	TANK,SUPPORT BEND	خزان الوقود

DEFECT	REMARKS	
02.K Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
03 Seats Condition		المقاعد
03.A Seat Condition	EXTRA COVER PORTION DAMAGED	حالة المقاعد
04 Tires and Rims Condition		الاطارات
04.A Rear Tyre	BOTH SIDE 2018,2019,CRACKED	الاطار الخلفي
04.B Front Tyre	BOTH SIDE 2019,CRACKED	الاطار الامامي
05 Interior Condition		الحالة الداخلية
05.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
05.B Sun Visor	RIGHT SIDE LOOSE	حاجب الشمس
05.C Other	CIGARETTE CONSOLE BOX DAMAGED,LOOSE	اخرى
05.D AC Condition	NOT WORKING	المكيف
06 Chassis Condition		الشاسي
06.A Chassis	OK	الشاسيه
07 Steering Condition		المقود
07.A Steering Boot	BOOT CUT	ربلة المقود
07.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
08 Suspension System		ممتص الصدمات
08.A Ball Joint	BOOT CUT	مفصل كروي
08.B Arms	LOWER ARM BUSHES CRACKED	ازرع
09 Engine Condition		المحرك
09.A Visual Engine Condition	REFITTED,ABNORMAL NOISY	حالة المحرك النظري
09.B Smoke	WHITE SMOKE	دخان
09.C Mount	MOUNT BUSHES CRACKED	كرسي
10 Exhaust System		نظام العادم
10.A Other	BRACKET RUBBER CUT & EXHAUST LOOSE	اخرى
11 Lights		الاضاءة
11.A Head Light	LENS FADED	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

