CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3012373
Transaction Date	20 Nov 2026, 16:37:16
Site Name	840 - Emirates Auctions
Transaction Number	72542325 (CC10009) (CC10019)



Vehicle Details

Chassis Number	ZN6XU61F7K*******
Specification	GCC Specification
Make	Maserati
Model	Levante
Model Year	2019
Color	Blue
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.B Doors	REAR LEFT SIDE REPAINTED,	أبواب
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR PORTION DENT , CHASSIS FLOOR COMPLETELY COVERED NOT VISIBLE, BODY LEVEL LOW	الارضية
01.E Bumper	MISALIGN,PORTION CRACKED	دعامية
01.F Sign of front accident	FRONT BUMPER FRAME BULK HEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS NOT CHECKED COMPLETELY COVERED MUDDY BODY LEVEL LOW NOT VISIBLE PROPERLY	الشاسيه
02.B Other	REMOVE ALL UNDER CHASSIS FENDER FLOOR COVERS FOR RECHECK PROPERLY	اخري
02.C Chassis Number	CHECKED ON STICKER	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED MINOR OIIL LEAK REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Exhaust System		نظام العادم
04.A Other	MIDDEL SUPPORT BEND	اخري

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY, NOT CHECKED	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2024 & RIGHT SIDE 2022 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACKED	الاطار الخلفي
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED SUSPENSION RUSTY REFITTED	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحاله الداخليه
08.A Other	INNER PARTS GETTING RUSTY MUDDY , WATER FLOODED	اخري
08.B AC Condition	NOT CHECKED	المكيف
08.C Dash Board	PORTION LOOSE	لوحة القياده

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae