



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 Jan 2022, 18:14:55
Transaction Number	48017110 (CC10006)	Queue Number	312309



Chassis Number	WAUAV54L19D013155
Engine Number	
Vehicle Class	Car
Manufacturer	Audi
Model	Q7
Model Year	2009
Color	Black
Mileage	155402 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Dash Board	REAR BOTH SIDE SIGRATE BOX DAMAGED	لوحة القيادة
01.B Mirror	BOTH SIDE AUTO NOT WORKING	المرايا
01.C Other	CENTER LIGHT COVER LOOSE	اخرى
01.D Roof Ceiling	PORTION DAMAGED & LOOSE	بطانه السقف
01.E Sunroof	NOT WORKING & CURTAIN HANDLE DAMAGED	فتحت سقف
02 Steering Condition		المقود
02.A Steering Box	STEERING HARD	جهاز المقود
02.B Steering Oil	OIL LEAK DRIPPING	زيت المقود
02.C Steering Boot	BOOT DRIPPING	ربلة المقود
03 Body		جسم المركبة
03.A Bumper	REPAINTED	دعامية
03.B Bonnet	REPAINTED & PORTION FADED	غطاء المحرك
03.C Trunk	PORTION REPAIRED & REPAINTED	صندوق
03.D Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
03.E Doors	REAR LEFT SIDE CURTAIN DAMAGED & RIGHT SIDE MISSING	أبواب

DEFECT	REMARKS	
04 Chassis Condition		الشاصي
04.A Chassis	CHASSIS OILY MUDY VISABLE AREA OK	الشاصيه
05 Transmission Condition		الجير
05.A Gear Box	GEAR KNOB COVER DAMAGED	الجير
06 Wipers and Arms		المساحات
06.A Wiper Arm &Blade	LEFT SIDE MISSING & RIGHT SIDE WORN OUT	ازرع المساحات والشفرات
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE LOW & HIGH BEAM NOT WORKING	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
08 Seats Condition		المقاعد
08.A Seat Condition	REAR RIGHT HEAD REST LOOSE	حالة المقاعد
09 Engine Condition		المحرك
09.A Engine Condition	OIL LEAK DRIPPING	حالة المحرك
10 Suspension System		ممتص الصدمات
10.A Arms	FRONT LOWER ARM BUSHES CUT	ازرع
11 Tires and Rims Condition		الاطارات
11.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
11.B Rear Tyre	BOTH SIDE 2018/2011 CRACKED & EXPIRED	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.