



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	13 Jan 2022, 18:08:04
Transaction Number	56996808 (CC10006)	Queue Number	312309



Chassis Number	JA3AU16U08U008000
Engine Number	
Vehicle Class	Car
Manufacturer	Mitsubishi
Model	Lancer
Model Year	2008
Color	Silver
Mileage	222980 Miles
Fuel Type	Petrol
No. Of Cylinders	4
Specification	USA Imported

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Rims Condition	RIMS HAVE MINOR DENT SCRATCHES & FRONT & REAR 2 NUT & 1 WHEEL HUB COVER MISSING	حالة الجنوط
01.B Front Tyre	BOTH SIDE 2019	الاطار الامامي
01.C Rear Tyre	BOTH SIDE 2020 MINOR CRACKED & WORN OUT	الاطار الخلفي
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Gear Box Mount	LOWER MOUNT BUSHES CRACKED	كرسي الجير
02.C Gear Box	PART GETTING RUSTY	الجير
03 Seats Condition		المقاعد
03.A Seat Belt	OK	حزام الأمان
03.B Seat Condition	FRONT LEFT SIDE MINOR DAMGED,DIRTY	حالة المقاعد
04 Steering Condition		المقود
04.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
05 Body		جسم المركبة
05.A Floor	MINOR DENT & BOTH RUNNING BOARD & REAR QUATER PANEL REPAIRED, RUSTY	الارضية

DEFECT	REMARKS	
05.B Paint	BODY TOTALY,REPAINTED,PORTION REPAIRED , MINOR DENTS, SCRATCHES	الصبغ
05.C Doors	FRONT & REAR BOTH SIDE REPAINTED,PORTION REPAIRED,REFITTED	أبواب
05.D Trunk	REPAINTED,PORTION REPAIRED,REFITTED	صندوق
05.E Fenders	FRONT & REAR BOTH SIDE REPAIRED,REPAINTED	مدكار
05.F Bonnet	REPAIRED,REPAINTED	غطاء المحرك
05.G Roof	REPAINTED,PORTION REPAIRED	السقف
05.H Sign of side accident		وجود مؤشر لحادث في الجانب
05.I Bumper	REPAINTED & FRONT RIGHT SIDE GRILL MISSING	دعامية
05.J Other	FRONT RADIATOR SUPPORT REPAIRED BEND	اخرى
05.K Sign of front accident		وجود مؤشر لحادث في المقدمة
06 Interior Condition		الحالة الداخلية
06.A AC Condition	OK & LEFT SIDE GRILL DAMAGED	المكيف
06.B Steering Wheel and control buttons	WORN OUT & HORN NOT WORKING	عجلة القيادة وازرار التحكم
06.C Audio	NOT WORKING	صوتيات
06.D Air Bag	LEFT SIDE AIR BAG DAMAGED ,MISSING	وسائد هوائية
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
07.B Head Light	RIGHT SIDE LIGHT BRACKET DAMAGED & LIGHTS ALWAYS ON	الاضاءة الرئيسية
07.C Other	ALL LIGHT WORKING	اخرى
08 Wipers and Arms		المساحات
08.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
08.B Other	WATER TANK CAP MISSING	اخرى
09 Suspension System		ممتص الصدمات
09.A Ball Joint	BOOT CUT	مفصل كروي
09.B Shock Absorber	FRONT BOTH SIDE OIL LEAK	ممتص الصدمات
09.C Arms	FRONT&REAR LOWER ARM BUSHES CRACKED	ازرع
09.D Other	FRONT STABILIZER LINK BOOT CUT	اخرى
10 Chassis Condition		الشاسي
10.A Chassis	OK	الشاسيه
11 Brake Condition		الفرامل
11.A Disc&Drum	GETTING RUSTY	دسك ووطنابير الفرامل
11.B Break Pads	GETTING WEAR	سفايف الرامل
12 Exhaust System		نظام العادم
12.A Other	LEAK &JOINT ONE BOLT MISSING	اخرى

DEFECT	REMARKS	
13 Engine Condition		المحرك
13.A Engine Condition	PART GETTING RUSTY&ABNORMAL NOISE ,SHAKING	حالة المحرك
14 Battery Condition		حالة البطارية
14.A Battery Condition	OK	حالة البطارية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



✓ PASS



Plate Details :	R 23731 Dubai Private
Chassis No :	JA3AU16U08U008000
Vehicle Make :	MITSUBISHI
Vehicle Model :	LANCER
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Silver
Drive Direction :	--
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	222961 Kms.
Origin :	Japan
Model Year :	2008
Gear Type :	Automatic
Engine Size :	2000 CC
Engine No :	NILL
Horse Power :	152
Axles No :	2
Cylinders :	4
No Of Doors :	4
No Of Seats :	5
G. V. W. :	1700 Kgs.
Empty Weight :	1147 Kgs.

Certificate Number :	1-CAR-2022-15864394
Inspection Date :	11-01-2022
Certificate Print Date :	11-01-2022
Services :	Renewal Test
Vehicle Testing Partner :	AG Cars
Vehicle Testing Center :	AG Cars Al Mamzar
Total Time Taken :	12 min 57 sec
Appointment Ref Number :	--
Start Time :	8:28
End Time :	8:40
Lane :	04
Token No. :	107
Attempt :	1
Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Vehicle Consumption (last 12 Months)

8931 KM	635 L	1029 AED	1.6 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 3 %	Service brake imbalance on rear axle 18 %	Parking brake imbalance between LHS and RHS 2 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 0 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Front Registration plate for Renewal	Paint faded	Minor

Inspection Remarks:

FRONT BUMPER FRAME RADIATOR SUPPORT BULK HEAD BOTH SIDE FENDER FRAME FENDER APRON LEFT SIDE C PILLAR,RUNNING BOARD AREA REPAIRED.MINOR SCRATCHES ON BODY.

Payment Details

Inspection Performed by 35215	Payment Method Cash	Transaction Number 15864394	Service Fees AED 170 Collected on 11/01/2022
Parking Slot No --	Service Name Renewal Test	Attempt 1	Received by Mary Antony

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

