



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	06 Sep 2022, 11:06:11
Transaction Number	77578418 (CC10008)	Queue Number	312309



Chassis Number	1G1FH1R79L0105254
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Camaro
Model Year	2020
Color	Green
Mileage	60212 Miles
Fuel Type	Petrol
No. Of Cylinders	8
Specification	USA Imported

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	REFITTED	حالة الجير النظرى
02 Suspension System		ممتص الصدمات
02.A Suspension Subframe	FRONT SUB/FRAME ,BOTH SIDE CRACKED,REAR RIGHT SIDE LOWER CONTROL ARM REPAIRED ,,DENT .	
02.B Ball Joint	BOOT CUT	مفصل كروي
03 Exhaust System		نظام العادم
03.A Modification	REWELDED NOISY	تعديلات
04 Body		جسم المركبة
04.A Floor	FLOOR PORTION DENT DETACHED UNDER PIPES LOOSE. REAR SUSPENSION REFITTED	الارضية
04.B Sign of back accident		وجود مؤشر لحادث في الخلف
04.C Sign of side accident		وجود مؤشر لحادث في الجانب
04.D Pillars	LEFT SIDE DOOR PILLAR OUTER PANEL ROCKER PANELQUARTER PANEL REPAIRED ,REPAINTED	القوائم
04.E Fenders	REFITTED	مدكار

DEFECT	REMARKS	
04.F Paint	BODY REPAINTED REPAIRED,MINOR DENT,SCRATCHES	الصبغ
04.G Sign of front accident		وجود مؤشر لحادث في المقدمة
04.H Bumper	REAR BUMPER FRAME ,BACK PANEL, QUARTER PANEL COMPARTMENT PANEL WHEEL ARCH .FRONT BULKHEAD ,FENDER FRAME REPAIRED.	دعامة
04.I Doors	LEFT SIDE REFITTED	أبواب
04.J Bonnet	REFITTED	غطاء المحرك
05 Interior Condition		الحالة الداخليه
05.A AC Condition	OK	المكيف
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2019 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي
07 Chassis Condition		الشاسي
07.A Chassis Number	CHASSIS NUMBER STICKER REFITTED	رقم القاعدة
07.B Chassis	REAR LEFT SIDE CHASSIS LOWER EDGE DENT & EXTENSION REPAIRED	الشاسيه
08 Engine Condition		المحرك
08.A Visual Engine Condition	REFITTED	حالة المحرك النظري
09 Steering Condition		المقود
09.A Tie Rod	BALL JOINT BOOT CUT	رودات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.