



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	14 Oct 2021, 17:48:35
Transaction Number	92211864 (CC10006)	Queue Number	312309



Chassis Number	WP1ZZZ9PZ8LA50967
Engine Number	
Vehicle Class	Car
Manufacturer	Porsche
Model	Cayenne
Model Year	2008
Color	White
Mileage	0 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	PORTION REPAIRED & REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Doors	PORTION REPAIRED & REPAINTED	أبواب
01.D Trunk	PORTION REPAIRED, REPAINTED & SHOCK WEAK	صندوق
01.E Bonnet	HANDLE DAMAGED	غطاء المحرك
01.F Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.G Bumper	REPAIRED & REPAINTED	دعامية
01.H Other	FRONT FENDER FRAME, BUMPER FRAME REPAIRED	اخرى
01.I Floor	UNDER FLOOR PORTION COVER	الارضية
02 Chassis Condition		الشاسي
02.A Chassis	FRONT BOTH SIDE OILY ,SHEILD COVER VISABLE AREA OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Condition	OIL LEAK	حالة المحرك
03.B Other	UNDER ENGINE COVER DAMAGED	اخرى
04 Seats Condition		المقاعد

DEFECT	REMARKS	
04.A Seat Condition	OK	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box	OIL LEAK	الجير
05.B Gear Box Mount	BUSHES CRACKED	كرسي الجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2017 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2017 CRACKED	الاطار الخلفي
06.C Rims Condition	REAR LEFT SIDE INNER MINOR BEND	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Wiper Arm & Blade	OK	ازرع المساحات والشفرات
08 Lights		الاضاءة
08.A Head Light	RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Disc&Drum	GETTING RUSTY	دسك ووطنابير الفرامل
09.B Brake Oil	FRONT RIGHT SIDE LEAK	زيت الفرامل
10 Suspension System		ممتص الصدمات
10.A Suspension Subframe	SUSPENTION SUB FRAME GETTING RUSTY & BOTH SIDE BUSHES CRACKED	
11 Steering Condition		المقود
11.A Steering Boot	LEAKING	ربلة المقود
12 Interior Condition		الحالة الداخليه
12.A Sun Visor	LEFT SIDE LOSE	حاجب الشمس
12.B Mirror	AUTO NOT WORKING	المرايا
12.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.