

## **TEST CERTIFICATE**

Site Number Transaction Number

04.A Head Light

**840-Emirates Auctions** 59186403 (CC10006)

Transaction Date

02 Aug 2022, 11:32:54

Queue Number 312309

Chassis Number

MMBENKA50FD056115

Engine Number

Vehicle Class Car

Manufacturer Mitsubishi

Model

Model Year

2015

Color

White

Mileage

62221 Km

Fuel Type

**Petrol** 

No. Of Cylinders

Specification

**GCC** Specification

المقود

**REMARKS DEFECT** 

O1 Body		جسم المركبة
01.A Paint	BODY MINOR DENT ,SCRATCHES & PORTION RUSTY	الصبغ
01.B Bumper	MISALIGN	دعامية
01.C Rusty	UNDER BODY PARTS, SUSPENSION, CHASSIS GETTING	صدأ

**RUSTY** 

**02 Transmission Condition** الجير

02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box	ОК	حالة الجير النظرى
Condition		

## **03 Tires and Rims Condition** الاطارات

03.A Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2020	الاطار الامامي

## **04 Lights** الاضاءة

الاضاءة الرئيسية **05 Steering Condition** 

LENS FADED

05.A Tie Rod End **BOOT CRACK** مؤخرة الرودات

DEFECT	REMARKS	
06 Chassis Condition		الشاصي
06.A Chassis	OK & GETTING RUSTY	الشاسيه
07 Interior Condition		الحاله الداخليه
07.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
07.B AC Condition	OK	المكيف
08 Suspension System		ممتص الصدمات
08.A Ball Joint	BOOT CRACK	مفصل کروي
08.B Arms	LOWER ARM BUSH CRACKED	ازرع
08.C Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	
09 Engine Condition		المحرك
09.A Visual Engine Condition	OIL WET	حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
  Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.