



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	27 Jul 2022, 12:02:41
Transaction Number	51016878 (CC10006)	Queue Number	312309



Chassis Number	KL1PJ5C58EK590015
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Cruze
Model Year	2014
Color	Silver
Mileage	129362 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
01.B Sign of front accident		وجود مؤشر لحادث في المقدمة
01.C Fenders	PORTION REPAIRED,REPAINTED & FRONT REFITTED	مدكار
01.D Bonnet	REFITTED	غطاء المحرك
01.E Trunk	PORTION REPAIRED,REPAINTED	صندوق
02 Interior Condition		الحالة الداخلية
02.A AC Condition	OK & GRILL ADJUSTMENT BUTTON MISSING	المكيف
02.B Mirror	VIEW MIRROR LOOSE & MINOR FADED	المرآيا
02.C Sun Visor	RIGHT SIDE GLASS COVER MISSING	حاجب الشمس
03 Transmission Condition		الجير
03.A Visual Gear Box Condition	OIL LEAK& REFITTED	حالة الجير النظري
03.B Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
03.C Road Test	NOT CHECK	فحص علي الطريق
04 Suspension System		ممتص الصدمات

DEFECT	REMARKS	
04.A Ball Joint	BOOT CRACKED	مفصل كروي
04.B Arms	LOWER ARM BUSH CRACKED	ازرع
05 Chassis Condition		الشاسي
05.A Chassis	FRONT LEFT SIDE CHASSIS LOWER PORTION MINOR BULGED	الشاسيه
06 Seats Condition		المقاعد
06.A Seat Condition	DRIVER SEAT MINOR CUT	حالة المقاعد
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2018 & CRACKED	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
08 Lights		الاضاءة
08.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
09 Engine Condition		المحرك
09.A Visual Engine Condition	OIL LEAK& REFITTED	حالة المحرك النظري
09.B Mount	MOUNT RUBBER CRACKED	كرسي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	--
Chassis No :	KL1PJ5C58EK590015
Vehicle Make :	CHEVROLET
Vehicle Model :	CRUZE
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Silver
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	129363 Kms.
Origin : South Korea	Model Year : 2014
Gear Type : Automatic	Engine Size : 1400 CC
Engine No : 140710469	Horse : 140
Axles No : 2	Power :
No Of : 4	Cylinders : 6
Doors :	No Of Seats : 5
G. V. W. : 2000 Kgs.	Empty : 1365 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17317245		
Inspection Date :	01-08-2022		
Certificate Print Date :	01-08-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	11 min 17 sec		
Appointment Ref Number :	--		
Start Time :	15:19	End Time :	15:31
Lane :	01	Token No. :	192
Attempt :	1	Prints No. :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
6 %	0 %	1 %	0 %
Vehicle on Petrol HC Reading			
0 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Pedal brake pedal spongy	Hard/spongy	Major

Discrepancies	Old Value	New Value	Verified
Engine Cylinders Incorrect number of cylinders	6	4	

Inspection Remarks: minor engine oil leak //,

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
3104 30544	VTP Credit Account	17317245	AED 170 Collected on 01/08/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لأي عمليات أخرى بما في ذلك أعراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

