



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	05 Jan 2022, 17:45:19
Transaction Number	57154988 (CC10006)	Queue Number	312309



Chassis Number	JN8FY1NY4GX012942
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2016
Color	Silver
Mileage	135335 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
01.B Mirror	OK	المرايا
02 Wipers and Arms		المساحات
02.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات
03 Seats Condition		المقاعد
03.A Seat Condition	REAR SEAT MISSING	حالة المقاعد
04 Lights		الاضاءة
04.A Head Light	OK	الاضاءة الرئيسية
04.B Tail Light	OK	الانارة
05 Body		جسم المركبة
05.A Fenders	LEFT SIDE BOTH PORTION REPAIRED , REPAINTED & REAR RIGHT SIDE REPAINTED	مدكار
05.B Doors	FRONT BOTH SIDE PORTION REPAINTED & REAR BOTH SIDE PORTION REPAIRED, REPAINTED	أبواب
05.C Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ

DEFECT	REMARKS	
05.D Bumper	REPAINTED	دعامية
05.E Bonnet	SHOCK WEAK	غطاء المحرك
05.F Rusty	UNDER BODY PARTS , CHASSIS , SUSPENTION GETTING RUSTY	صدأ
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
07 Engine Condition		المحرك
07.A Engine Condition	OIL LEAK , REFITTED & MISFIRING	حالة المحرك
07.B Smoke	WHITE SMOKE	دخان
08 Transmission Condition		الجير
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Gear Box	GARCKING	الجير
09 Steering Condition		المقود
09.A Steering Box	ROMANO LEAKING	جهاز المقود
09.B Other	STABILIZER LINK BUSHES DRY CRACKED	اخرى
10 Suspension System		ممتص الصدمات
10.A Arms	REAR CONTROL ARMS BUSHES CRACKED	ازرع
11 Chassis Condition		الشاسي
11.A Chassis	CHASSIS FRAME COMPLETLY PORTION RUSTY & PAINT	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details : C 92567 Ras Al Khaymah Private

Chassis No : JN8FY1NY4GX012942

Vehicle Make : NISSAN

Vehicle Model : PATROL

Vehicle Class : Light Vehicle

Body Type : STATION

Fuel : Benzene

Color : Silver

Drive Direction : --

Dimensions : (H x W x L) -- x -- x --

Current Odometer : 135342 Kms.

Origin : Japan Model Year : 2016

Gear Type : Manual Engine Size : 3500 CC

Engine No : tb48089159 Horse Power : --

Axles No : 2 Cylinders : 6

No Of Doors : 4 No Of Seats : 7

G. V. W. : 1900 Kgs. Empty Weight : 1400 Kgs.

Certificate Number : 5-TAS-2022-15869300

Inspection Date : 11-01-2022

Certificate Print Date : 11-01-2022

Services : Registration Test

Vehicle Testing Partner : Tasjeel

Vehicle Testing Center : Tasjeel Al Aweer

Total Time Taken :
12 min 51 sec

Appointment Ref Number : --

Start Time : 15:13

End Time : 15:26

Lane : 03

Token No. : 186

Attempt : 1

Prints No : 1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)



12744 KM

Distance per
year



1312 L

Fuel consumed
per year



2126 AED

Fuel cost per
year



3.2 ton

Carbon footprint
per year

Parameter Readings

Service brake imbalance on
front axle
30 %

Service brake imbalance on
rear axle
28 %

Parking brake imbalance
between LHS and RHS
47 %

Vehicle on Petrol CO
Reading
0.04 %

Vehicle on Petrol HC
Reading
12 PPM VOL

Inspection Findings

Discrepancies

Engine Size Discrepancy in Engine Size

Old Value

3500

New Value

4800

Verified

Inspection Remarks: MINOR ENGINE OIL LEAK / CHASSIS MINOR RUSTY REPAINTED/ RR CHASSIS MINOR BULGE

Payment Details

Inspection Performed by
62439

Payment Method
VTP Credit Account

Transaction Number
15869300

Service Fees
AED 170 Collected on 11/01/2022

Parking Slot No
--

Service Name
Registration Test

Attempt
1

Received by
Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

