



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **13 Mar 2023, 13:36:07**  
 Transaction Number **62242572 (CC10008)** Queue Number **686959**



Chassis Number **WBA7T2A06MCF93254**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **BMW**  
 Model **750LI**  
 Model Year **2021**  
 Color **Blue**  
 Mileage **14982 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **6**  
 Specification **GCC Specification**

| DEFECT                           | REMARKS                                     |                   |
|----------------------------------|---|-------------------|
| <b>01 Interior Condition</b>     |   | الحاله الداخليه   |
| 01.A AC Condition                | OK  | المكيف            |
| <b>02 Lights</b>                 |   | الاضاءة           |
| 02.A Warning Light               | WARNING LIGHT ON IN DISPLY                  | ضوء تحذير         |
| <b>03 Seats Condition</b>        |   | المقاعد           |
| 03.A Seat Condition              | FRONT BOTH SIDE SEAT ADJUSTMENT NOT WORKING | حالة المقاعد      |
| <b>04 Body</b>                   |   | جسم المركبة       |
| 04.A Paint                       | BODY MINOR DENT SCRATCHES                   | الصبغ             |
| 04.B Bonnet                      | REFITTED                                    | غطاء المحرك       |
| 04.C Vehicle Model               | 740 LIA                                     | طراز المركبة      |
| <b>05 Transmission Condition</b> |   | الجير             |
| 05.A Visual Gear Box Condition   | REFITTED                                    | حالة الجير النظري |
| 05.B DIFFERENTIAL                | MINOR OIL LEAK                              | الدفرنشل          |
| 05.C Road Test                   | NOT CHECK                                   | فحص علي الطريق    |
| <b>06 Suspension System</b>      |   | ممتص الصدمات      |

| DEFECT                             | REMARKS                          |                          |
|------------------------------------|----------------------------------|--------------------------|
| 06.A Other                         | BODY LEVEL LOW                   | اخرى                     |
| <b>07 Tires and Rims Condition</b> |                                  | <b>الاطارات</b>          |
| 07.A Rear Tyre                     | BOTH SIDE 2020                   | الاطار الخلفي            |
| 07.B Front Tyre                    | BOTH SIDE 2020                   | الاطار الامامي           |
| <b>08 Chassis Condition</b>        |                                  | <b>الشاسي</b>            |
| 08.A Chassis                       | CHECKED VISIBLE AREA OK          | الشاسيه                  |
| <b>09 Engine Condition</b>         |                                  | <b>المحرك</b>            |
| 09.A Visual Engine Condition       | OIL LEAK,OPEN,REFITTED,OVER HEAT | حالة المحرك النظري       |
| 09.B Smoke                         | WHITE SMOKE                      | دخان                     |
| <b>10 Engine Cooling System</b>    |                                  | <b>نظام تبريد المحرك</b> |
| 10.A Coolant tank                  | COOLANT LEAK                     | خزان التبريد             |
| <b>11 Brake Condition</b>          |                                  | <b>الفرامل</b>           |
| 11.A Hand Brake                    | NOT WORKING                      | فرامل اليد               |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.