

Queue Number 2707010

Transaction Date 01 Sep 2026, 15:13:45

Site Name
840 - Emirates AuctionsTransaction Number
90338637 (CC10006) (CC10006)

Vehicle Details

Chassis Number	LGWCB3182L*****
Specification	GCC Specification
Make	Great Wall
Model	Wingle
Model Year	2020
Color	White
Mileage	139850 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body		جسم المركبة
01.A Paint	MINOR DENTS, SCRATCHES ,PORTION RUSTY ON BODY	الصبغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR RUST PROOFED	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED	دعامية
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS FRAME RUST PROOFED, PORTION RUSTY, PORTION DENT	الشاسية
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED	كرسي
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING . PARTS RUSTY	الحالة النظرية للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	REFITTED, OIL LEAK, PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Gear Box Mount	BUSH CRACKED	كرسي الجير
04.C Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACKED	الاطار الخلفي

Condition	Remarks	الحالة
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	LEAK	ممتص الصدمات
07.B Arms	BUSHES CRACKED	ازرع
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
08.B AC Condition	OK, GRAIL PORTION DAMAGED	المكيف
08.C Dash Board	PORTION DAMAGED	لوحة القيادة

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae