CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877740
Transaction Date	17 Oct 2026, 11:08:14
Site Name	840 - Emirates Auctions
Transaction Number	12397307 (CC10010) (CC10010)



Vehicle Details

Chassis Number	YV1AS9955A*******
Specification	GCC Specification
Make	Volvo
Model	S 80
Model Year	2010
Color	Black
Mileage	178257 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REAR RIGHT SIDE REPAINTED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	RIGHT SIDE DOOR PORTION REPAINTED.	أبواب
01.D Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.G Bonnet	REPAIRED REPAINTED.	غطاء المحرك
01.H Trunk	PORTION REPAINTED.	صندوق
01.I Sign of front accident	FRONT ASSEMBLY REFITTED .	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COMPLETE COVERED OILY MUDDY ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
02.B Chassis Number	VIN AREA GETTING RUSTY.	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Smoke	BLACK	دخان
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**

Condition	Remarks	الحالة
04.A Seat Condition	LOOSE PORTION CRACKED.	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACKED WORN OUT .	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES.	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED.	الاضاءة الرئيسية
07.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY WEAK	دواسة الفرامل
08.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	BOOT CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
10.C Axle	AXLE BOOT GREASE LEAKING.	اكسلات
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخري
11.B Mirror	LOOSE FADED. SIDE COVER DAMAGED	المرايا
11.C AC Condition	NOT CHECKED .	المكيف
11.D FLoor Matting	CENTER CONSOLE BOX DAMAGED.	فرش الأرضيه
11.E Dash Board	PORTION LOOSE ,SCREN DAMAGED NOT OPEN	لوحة القياده
11.F Roof Ceiling	LOOSE.	بطانه السقف
11.G Sun Visor	LOOSE.	حاجب الشمس
11.H Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.I Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.J Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the

يمكنك التحقق من صحة الشهادة عبر الرابط

link: carcheck.ae/certificate



carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**