

TEST CERTIFICATE

Site Number Transaction Number

control buttons

04 Body

04.A Bumper

840-Emirates Auctions 61220418 (CC10006)

Transaction Date

17 May 2023, 17:01:52

Oueue Number

716347



Chassis Number MDHBN7AD2FG720565

Engine Number

Vehicle Class Car

Manufacturer Nissan

Model Sunny

Model Year 2015

Color White

001 Km Mileage

Fuel Type Petrol

No. Of Cylinders

Specification **GCC Specification**

DEFECT REMARKS

01 Interior Condition الحاله الداخليه

01.A Steering Wheel and **WORN OUT** عجلة القيادة وازرار التحكم

01.B AC Condition **NOT CHECKED** المكيف

01.C Odometer reading **NOT CHECKED** قراءة عداد المسافات

02 Engine Condition المحرك

02.A Visual Engine Condition ENGINE NOT START, ALL SYSTEM NOT CHECKED, KEY حالة المحرك النظرى

MISSING, REFITTED, OIL LEAK

02.B Mount **BUSHES CUT** كرىسى

03 Tires and Rims Condition الاطارات

03.A Front Tyre **BOTH SIDE 2014 EXPIRED CRACKED** الاطار الامامى **BOTH SIDE 2020 CRACKED** 03.B Rear Tyre الاطار الخلفى

جسم المركبة MISALIGN, PORTION DAMAGE.

دعامية

04.B Sign of back accident وجود مؤشر لحادث في الخلف

04.C Paint BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT, SCRATCHES, PORTION FADED, PORTION RUSTY

الصبغ

DEFECT	REMARKS	
04.D Floor	BACK PANEL, QUATER PANEL REPAIRED	الارضية
04.E Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
05 Transmission Condition		الجير
05.A Gear Box Mount	BUSH CUT	كرسي الجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
05.C Visual Gear Box Condition	NOT CHECKED	حالة الجير النظرى
06 Suspension System		ممتص الصدمات
06.A Shock Absorber	UPPER MOUNT BUSHES CUT	ممتص الصدمات
06.B Arms	LOWER ARM BUSHES CUT	ازرع
06.C Ball Joint	BOOT CUT	مفصل كروي
07 Lights		الاضاءة
07.A Head Light	LENS FADED,ALL LIGHTS NOT CHCKED.	الاضاءة الرئيسية
08 Chassis Condition		الشاصي
08.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.