

TEST CERTIFICATE

19 Jul 2022, 13:24:59

مدكار

Site Number **840-Emirates Auctions** Transaction Date

Transaction Number 81315960 (CC10006) Queue Number 312309



Chassis Number 1FAHP2E84EG186462

Engine Number

Vehicle Class Car Manufacturer **Ford** Model **Taurus**

2014 Model Year

Color White

148408 Miles Mileage

Fuel Type **Petrol**

No. Of Cylinders

Specification **USA** Imported

DEFECT **REMARKS**

01 Tires and Rims Condition				
01.A Rear Tyre	BOTH SIDE 2020	الاطار الخلفي		
01.B Front Tyre	BOTH SIDE 2020 WORN OUT	الاطار الامامي		
O2 Body		جسم المركبة		
02.A Floor	UNDER FLOOR HAVE DENT	الارضية		
02.B Paint	BODY REPAINTED PORTION REPAIRED , MINOR DENTS SCRATCHES	الصبغ		
02.C Doors	FRONT LEFT SIDE & REAR RIGHT SIDE PORTION REPAIRED	أبواب		

& REPAINTED 02.D Other FRONT BUMPER FRAME BULK HEAD FENDER FRAME اخري RADIATOR SUPPORT REPAIRED

02.E Sign of front accident وجود مؤشر لحادث في المقدمة

LEFT SIDE BOTH PORTION REPAIRED, REPAINTED & FRONT 02.F Fenders

BOTH SIDE REFITTED

02.G Bonnet REPAIRED, REPAINTED & REFITTED غطاء المحرك

03 Engine Condition المحرك

03.A Visual Engine Condition MINOR OIL LEAK حالة المحرك النظرى

04 Transmission Condition الجير

DEFECT	REMARKS	
04.A Gear Box Mount	MOUNT BUSH CRACKED	كرسي الجير
04.B Road Test	NOT CHECK	فحص علي الطريق
04.C Visual Gear Box Condition	OK	حالة الجير النظرى
05 Suspension System		ممتص الصدمات
05.A Ball Joint	BOOT CUT	مفصل كروي
05.B Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
06 Steering Condition		المقود
06.A Tie Rod End	BOOT CUT	مؤخرة الرودات
07 Chassis Condition		الشاصي
07.A Other	FOR RECHECK REMOVE FRONT FENDER UNDER ENGIEN COVERS	اخري
07.B Chassis	FRONT RIGHT SID CHASSIS INNER MINOR DENT &LEFT SIDE INNER SUPPORT REPAIRED	الشاسيه
08 Interior Condition		الحاله الداخليه
08.A AC Condition	ОК	المكيف
08.B Air Bag	DAMAGED	وسائد هوائية
09 Lights		الاضاءة
09.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate









Plate Details: 1FAHP2E84EG186462 Chassis No: Vehicle Make: FORD Vehicle Model: **TAURUS** Vehicle Class: Light Vehicle **Body Type:** SALOON Fuel: Benzene Color: White **Drive Direction:** Dimensions: (H x W x L) --x--x--**Current Odometer:** 238844 Kms. Origin: United States Model Year: 2014 Engine Size: 3500 CC Gear Type: Automatic Engine No: nil Horse 288 Power: Axles No: Cylinders: 6 No Of No Of Seats: 5 Doors: G. V. W. : 2000 Kgs. **Empty** 1500 Kgs. Weight:

Certificate Number:		5-TAS-2022-17242749		
Inspection Date :		20-07-2022		
Certificate Print Date :		20-07-2022		
Services :		Registration Test		
Vehicle Testing Partner:		Tasjeel		
Vehicle Testing Center:		Tasjeel Al Aweer		
Total Time Taken:		2 min 29 sec		
Appointment Ref Number :				
Start	18:18	End Time: 18:20		
Time :		Token No.: 234		
Lane:	01	Prints No: 1		
Attempt	2			

Inspection Findings

Defects	Issue	Severity
Dip beams (Low Beams) headlight repair left side low beam	Defective	Major
Vehicle Floor repair middle floor both side dent	Others (Major)	Major
Warning triangle warning triangle not found	Missing	Major

Inspection Remarks: front bulkhead/bonnet/ front left side fender& frame& apron repaired

Payment Details			
Inspection Performed by	Payment Method	Transaction Number	Service Fees
3104	Cash	17242749	AED 70 Collected on 20/07/2022
Parking Slot No	Service Name	Attempt	Received by
	Registration Test	2	Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية
ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أُصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال
30. يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.