CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934039
Transaction Date	02 Nov 2026, 14:28:14
Site Name	840 - Emirates Auctions
Transaction Number	72693965 (CC10009) (CC10019)



Vehicle Details

Chassis Number	WAUSHC4G5D*******
Specification	GCC Specification
Make	Audi
Model	A7
Model Year	2013
Color	White
Mileage	145686 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REPAINTED,PORTION REPAIRED ,FRONT RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES	الصبغ
01.C Doors	FRONT LEFT SIDE ,REAR BOTH SIDE REPAINTED,PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR PORTION DENT	الارضية
01.F Bumper	MISALIGN PORTION DAMAGED,PART MISSING	دعامية
01.G Bonnet	SHOCK NOT WORKING	غطاء المحرك
01.H Trunk	REAR SWITCH NOT WORKING PROPERLY	صندوق
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY MINOR SHAKING	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	FRONT BOTH SIDE HEAD REST COVER PORTION LOOSE	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	MINOR OIL LEAK OPEN REFITTED	الحالة النظريه للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		**الاضاءة**
07.A Tail Light	RIGHT SIDE PORTION CRACK	الضوء الخلفي
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Interior Condition		**الحاله الداخليه**
08.A Other	CENTER CONSOLE BOX LOCK DAMAGED & INTERIOR METAL PARTS RUSTY	اخري
08.B AC Condition	OK	المكيف
08.C Audio	AUTO FOLDING NOT WORKING	صوتيات
08.D Dash Board	PORTION WORN OUT	لوحة القياده
08.E Roof Ceiling	PORTION LOOSE	بطانه السقف
08.F Sun Visor	LEFT SIDE PORTION DAMAGED,RIGHT MISSING	حاجب الشمس
08.G Door Panel	PORTION GETTING WORN OUT	لوحة بطانة الباب
08.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.I Gear Shifting Lever	KNOB GETTING WORN OUT	ذراع نقل السرعات
08.J Engine Start Button	WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae