



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>04 Sep 2022, 17:53:33</b>
Transaction Number	<b>83778006 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WP1ZZZ92ZGLA78523</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Porsche</b>
Model	<b>Cayenne</b>
Model Year	<b>2016</b>
Color	<b>Black</b>
Mileage	<b>132073 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Sign of front accident		وجود مؤشر لحادث في المقدمة
01.B Paint	REPAINTED PORTION REPAIRED MINOR DENTS SCRATCHES ON BODY	الصبغ
01.C Floor	UNDER FLOOR CHASSIS FULLY COVERED CHECKED VISIBLE AREA	الارضية
01.D Fenders	FRONT BOTH SIDE PORTION REPAIRED, REPAINTED & REFITTED, RIGHT SIDE FENDER SKIRT LOOSE	مدكار
01.E Doors	FRONT LEFT SIDE PORTION REPAIRED,REPAINTED	أبواب
01.F Bonnet	PORTION REPAIRED,REPAINTED & REFITTED, SHOCKS WEAK	غطاء المحرك
01.G Trunk	PORTION REPAIRED,REPAINTED	صندوق
01.H Other	FRONT BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED	اخرى
01.I Pillars	RIGHT SIDE B PILLAR INNER COVER LOOSE	القوائم
<b>02 Interior Condition</b>		<b>الحالة الداخلية</b>
02.A AC Condition	OK & GRILL ADJUSTMENT BUTTON MISSING	المكيف
02.B Power Window Switch	FRONT LEFT SIDE BUTTON DAMAGED	مفتاح النافذه
02.C Mirror	VIEW MIRROR STAND COVER LOOSE	المرابا

DEFECT	REMARKS	
<b>03 Steering Condition</b>		<b>المقود</b>
03.A Axle	BOOT LEAK	اكسلات
03.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
03.C Steering Oil	OIL LEAK	زيت المقود
03.D Steering Boot	BOOT CUT	ربلة المقود
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Visual Gear Box Condition	OIL LEAK REFITTED	حالة الجير النظرى
04.B Road Test	NOT CHECK	فحص علي الطريق
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	OIL LEAK REFITTED	حالة المحرك النظرى
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	LOWER ARM BUSHES CRACKED	ازرع
06.B Other	FRONT BODY LEVEL LOW & AUTO SUSPENSION NOT WORKING	اخري
<b>07 Chassis Condition</b>		<b>الشاصي</b>
07.A Chassis	FRONT LEFT SIDE CHASSIS END REPAIRED ,RIGHT SIDE OUTER MINOR DENT	الشاسيه
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Front Tyre	BOTH SIDE 2020/2021,CRACKED	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2020/2021	الاطار الخلفي
<b>09 Lights</b>		<b>الاضاءة</b>
09.A Warning Light	WARNING MESSAGE ON IN DISPLAY	ضوء تحذير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Change possession :	66773937
Chassis No :	WP1ZZZ92ZGLA78523
Vehicle Make :	PORSCHE
Vehicle Model :	CAYENNE
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	132075 Kms.
Origin : Germany	Model Year : 2016
Gear Type : Automatic	Engine Size : 3600 CC
Engine No : 007603	Horse 300
Axles No : 2	Power :
No Of 4	Cylinders : 6
Doors :	No Of Seats : 5
G. V. W. : 2600 Kgs.	Empty 2200 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17577733		
Inspection Date :	07-09-2022		
Certificate Print Date :	07-09-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	9 min 11 sec		
Appointment Ref Number :	--		
Start Time :	12:30	End Time :	12:40
Lane :	01	Token No. :	159
Attempt :	2	Prints No. :	1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate last 12 Months)

2912 KM	300 L	978 AED	0.8 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Inspection Remarks:

FRONT LEFT SIDE FRAME MEMBER REPAIRED. HAVING PASSED CCM REPORT. FRONT BULKHEAD, BUMPER FRAME, RADIATOR FRAME REPAIRED. MINOR BODY DENT & SCRATCHES

## Payment Details

Inspection Performed by 3104	Payment Method Cash	Transaction Number 17577733	Service Fees AED 70 Collected on 07/09/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

