



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 Jan 2023, 12:56:52
Transaction Number	16527440 (CC10009)	Queue Number	658853



Chassis Number	JN8BY2NY7K9195187
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2019
Color	Beige
Mileage	7853 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Engine Condition</b>		<b>المحرك</b>
01.A Visual Engine Condition	MINOR OIL LEAK REFITTED	حالة المحرك النظري
01.B Mount	MOUNT RUBBER CUT	كرسي
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Doors	REFITTED /MODIFIED	أبواب
02.B Trunk	REPAIRED REPAINTED /REFITTED MODIFIED / AUTO BUTTON NOT WORKING	صندوق
02.C Bonnet	MODIFIED , REFITTED , HAVE EXTRA DIFFERENT LOGO	غطاء المحرك
02.D Bumper	MODIFIED	دعامية
02.E Paint	BODY TOTALLY REPAINTED PORTION REPAIRED , MINOR DENTS SCRATCHES ON BODY/ MODIFIED	الصبغ
02.F Sign of back accident		وجود مؤشر لحادث في الخلف
02.G Floor	BODY MOUNT REFITTED	الارضية
02.H Fenders	REFITTED	مدكار
02.I Other	FRONT BUMPER FRAME RADIATOR SUPPORT REPAIRED BULK HEAD REFITTED ,BOLTS LOOSE	اخرى
02.J Sign of front accident		وجود مؤشر لحادث في المقدمة
<b>03 Transmission Condition</b>		<b>الجير</b>

DEFECT	REMARKS	
03.A Road Test	NOT CHECKED	فحص علي الطريق
03.B Visual Gear Box Condition	SIGN OF MINOR OIL LEAK REFITTED	حالة الجير النظري
03.C Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
03.D DIFFERENTIAL	REFITTED	الدفرنشل
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Rear Tyre	BOTH SIDE 2021 CRACKED	الاطار الخلفي
04.B Front Tyre	BOTH SIDE 2021 CRACKED	الاطار الامامي
<b>05 Chassis Condition</b>		<b>الشاسي</b>
05.A Chassis	REAR RIGHT SIDE LOWER BRACKET MINOR DNT , FRAME RUST PROOFED REAR PORITON MUDDY	الشاسيه
05.B Chassis Number	STICKER REFITTED . PORRTION DAMAGED	رقم القاعدة
<b>06 Interior Condition</b>		<b>الحاله الداخليه</b>
06.A Other	INTERIOR TOTALLY MODIFIED	اخرى
06.B Dash Board	MODIFIED	لوحة القيادة
06.C Steering Wheel and control buttons	MODIFIED/ ADJUSTMENT NOT WORKING	عجلة القيادة وازرار التحكم
06.D Roof Ceiling	PORTION LOOSE	بطانه السقف
<b>07 Lights</b>		<b>الاضاءة</b>
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.B Head Light	MODIFIED	الاضاءة الرئيسية
<b>08 Suspension System</b>		<b>ممتص الصدمات</b>
08.A Ball Joint	BOOT CUT	مفصل كروي
08.B Arms	LOWER ARM BUSHES CUT	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Plate Details : 9 38703 Abu Dhabi Private

Chassis No : JN8BY2NY7K9195187

Vehicle Make : NISSAN

Vehicle Model : PATROL

Vehicle Class : Light Vehicle

Body Type : STATION

Fuel : Benzene

Color : Brown, Piege

Drive Direction : --

Dimensions : (H x W x L) -- x -- x --

Current Odometer : 7854 Kms.

Origin : Japan

Model Year : 2019

Gear Type : Automatic

Engine Size : 4800 CC

Engine No : VQ40718940B

Horse 101

Axles No : 2

Power :

No Of 5

Cylinders : 4

Doors :

No Of Seats : 5

G. V. W. : 2150 Kgs.

Empty 1840 Kgs.

Weight :

Certificate Number : 5-TAS-2023-18620965

Inspection Date : 23-01-2023

Certificate Print Date : 23-01-2023

Services : Registration Test

Vehicle Testing Partner : Tasjeel

Vehicle Testing Center : Tasjeel Al Aweer

Total Time Taken : 17 min 19 sec

Appointment Ref Number : --

Start Time : 17:26

End Time : 17:44

Time :

Token No. : 239

Lane : 02

Prints No : 1

Attempt : 1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate in 12 Months)



1122 KM

Distance per  
year



116 L

Fuel consumed  
per year



403 AED

Fuel cost per  
year



0.3 ton

Carbon footprint  
per year

## Parameter Readings

Service brake imbalance on front axle

1 %

Service brake imbalance on rear axle

2 %

Parking brake imbalance between LHS and RHS

3 %

Vehicle on Petrol CO Reading

0.21 %

Vehicle on Petrol HC Reading

117 PPM VOL

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Seats Incorrect Number of Seats	5	7	
Engine Cylinders Incorrect number of cylinders	4	6	
Engine Size Discrepancy in Engine Size	4800	4000	

Inspection Remarks: under neath oil wetness // face lifted , old to new model // chassis minor rusty //

## Payment Details

Inspection Performed by 30544

Payment Method VTP Credit Account

Transaction Number 18620965

Service Fees AED 170 Collected on 23/01/2023

Parking Slot No --

Service Name Registration Test

Attempt 1

Received by Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

