



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	17 Apr 2022, 15:13:57
Transaction Number	49252410 (CC10006)	Queue Number	312309



Chassis Number	JN8AY25Y0B9010098
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2011
Color	Gold
Mileage	100406 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
01.B Front Tyre	BOTH SIDE 2021	الاطار الامامي
02 Interior Condition		الحالة الداخلية
02.A Air Bag	FRONT BOTH SIDE AIR BAG DAMAGED	وسائد هوائية
03 Body		جسم المركبة
03.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT SCRATCHES	الصبغ
03.B Doors	FRONT LEFT SIDE REPAINTED & REAR LEFT SIDE REPAIRED,REPAINTED & RIGHT SIDE BOTH PORTION REPAIRED,REPAINTED	أبواب
03.C Bumper	REPAINTED	دعامة
03.D Other	LEFT SIDE FOOTREST SKIRT DAMAGED	اخرى
03.E Fenders	FRONT LEFT SIDE REPAINTED , FRONT RIGHT SIDE & REAR BOTH SIDE PORTION REPAIRED,REPAINTED	مدكار
03.F Trunk	PORTION REPAIRED,REPAINTED	صندوق
04 Transmission Condition		الجير
04.A Road Test	NOT CHECKED	فحص علي الطريق

DEFECT	REMARKS	
04.B Visual Gear Box Condition	SIGN OF LEAK	حالة الجير النظري
04.C Gear Box Mount	MOUNT RUBBER MINOR CRACKED	كرسي الجير
05 Suspension System		ممتص الصدمات
05.A Arms	BOTH SIDE LOWER ARM BUSHES CRACKED	ازرع
06 Steering Condition		المقود
06.A Tie Rod End	BOOT CRACKED	مؤخرة الرودادات
06.B Steering Boot	BOOT CUT	ربلة المقود
07 Lights		الاضاءة
07.A Fog light	FRONT RIGHT SIDE NOT WORKING	كشفاف الضباب
08 Chassis Condition		الشاصي
08.A Chassis	OK	الشاسيه
09 Brake Condition		الفرامل
09.A Hand Brake	NOT WORKING	فرامل اليد
10 Seats Condition		المقاعد
10.A Seat Condition	DIVER SEAT LOWER COVER CRACKED	حالة المقاعد
11 Engine Condition		المحرك
11.A Visual Engine Condition	OIL LEAK , ABNORMAL NOISY	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.