



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>16 Mar 2023, 16:18:11</b>
Transaction Number	<b>89121673 (CC10009)</b>	Queue Number	<b>688626</b>



Chassis Number	<b>WAUZZZF82NN001284</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Audi</b>
Model	<b>S8</b>
Model Year	<b>2022</b>
Color	<b>Black</b>
Mileage	<b>7627 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Transmission Condition</b>		<b>الجير</b>
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	OK	حالة الجير النظرى
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A AC Condition	OK	المكيف
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2021	الاطار الامامي
<b>04 Body</b>		<b>جسم المركبة</b>
04.A Paint	OK	الصبغ
04.B Floor	UNDER FLOOR FENDER CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY/OK	الارضيه
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	OK	حالة المحرك النظرى
<b>06 Chassis Condition</b>		<b>الشاصي</b>

## DEFECT

## REMARKS

06.A Chassis

CHASSIS FULLY COVERED CHECKED VISIBLE AREA  
ONLY/OK

الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.