



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	24 Jan 2023, 14:57:06
Transaction Number	80966259 (CC10006)	Queue Number	660730



Chassis Number	KNAMB763466077334
Engine Number	
Vehicle Class	Car
Manufacturer	Kia
Model	Carnival
Model Year	2006
Color	Silver
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
01.B Tail Light	BROKEN.	الانارة
02 Interior Condition		الحالة الداخليه
02.A AC Condition	NOT CHECKED .	المكيف
02.B Odometer reading	NOT CHECKED .	قراءة عداد المسافات
03 Steering Condition		المقود
03.A Steering Oil	OIL LEAK .	زيت المقود
03.B Steering Boot	BOOT CUT .	ربلة المقود
04 Transmission Condition		الجير
04.A Road Test	NOT CHECKED .	فحص علي الطريق
04.B Visual Gear Box Condition	REFITTED OIL LEAK .	حالة الجير النظرى
05 Body		جسم المركبة
05.A Sign of front accident		وجود مؤشر لحادث في المقدمة
05.B Other	FRONT LEFT SUDE ,FENDER FRAME ,BUMPER FRAME ,RADIATOR SUPPORT REPAIRED.	اخرى

DEFECT	REMARKS	
05.C Door Handle &Lock	DOOR HANLD BROKEN ,MISSING ,REAR DOORS NOT OPEN PROPERLY	مقابض الأبواب والأقفال
05.D Paint	BODY PORTION REPAIRED ,REPAINTED ,DENTS SCRATCHES . PORTION FADED .	الصبغ
05.E Bumper	MISALIGN PORTION DAMAGED . GRILL DAMAGE LOOSE .	دعامية
05.F Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY ,	صدأ
05.G Floor	PORTION DENT .	الارضية
05.H Windshield	FRONT CRACKED .	زجاج
06 Tires and Rims Condition		الاطارات
06.A Rear Tyre	BOTH SIDE 2019 CRACKED .	الاطار الخلفي
06.B Front Tyre	BOTH SIDE 2021 CRACKED .	الاطار الامامي
07 Chassis Condition		الشاصي
07.A Chassis	VISIBLE AREA OK.	الشاسيه
08 Seats Condition		المقاعد
08.A Seat Condition	REAR RIGHT SIDE HEAD REST MISSING .	حالة المقاعد
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK ,WEAK .	ممتص الصدمات
09.B Arms	LOWER ARM BUSHES CRACKED ,	ازرع
10 Engine Condition		المحرك
10.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,OIL LEAK ,REFITTED	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.