

Queue Number

2895489

Transaction Date

23 Oct 2026, 10:13:27

Site Name

840 - Emirates Auctions

Transaction Number

34694781 (CC10026) (CC10026)



Vehicle Details

Chassis Number	5FNRL5H24G*****
Specification	Imported
Make	Honda
Model	Odyssey
Model Year	2016
Color	Silver
Mileage	96916 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH REPAINTED PORTION REPAIRED , FRONT SIDE REFITTED	مكدار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.F Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.G Bonnet	REFITTED , REPAINTED PORTION REPAIRED	غطاء المحرك
01.H Pillars	LEFT SIDE B PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Door Handle & Lock	LEFT SIDE DOOR LOCK DAMAGE	مقابض الأبواب والأقفال
01.J Fuel Tank	BADLY DENT	خزان الوقود
01.K Sign of front accident	BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS END REPAIRED , DENT , GETTING RUSTY	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	PARTS REFITTED PARTS GETTING RUSTY , SIGN OF OIL WET	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET , MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE DAMAGE	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
08.B AC Condition	OK	المكيف
08.C Dash Board	PORTION WORN OUT	لوحة القيادة
08.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
08.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
08.G Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae